

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24060006/UPA3Q2
Date: 19/09/2024

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7230008714		
Claimant Vehicle No :	SJY6436L	Insured Vehicle No :	SNJ4648L		
Date of Loss:	07/06/2024	Nature of Claim:	TP	Claim No:	9945157504SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY6436L	Engine No:	3ZZB011130
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106179922
Reg. Date:	21/09/2010 (Man. Year: 2010)	Odometer:	235979 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Toyo 5 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,224.75	1,312.33	912.42	41.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	700.00	1,680.00	70.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,604.75	2,012.33	2,592.42	56.30
Approved Total (Overridden) (S\$)		1,600.00		
Nett Amount (S\$)	4,604.75	1,600.00	3,004.75	65.25
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		1,752.18		
Global Sum Settlement (S\$)		1,750.00		

INSPECTION

Date of Assignment:	10/06/2024		
Date Inspected:	10/06/2024	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP LH	Holder Cracked	930.50 FL	*820.10 FL
2	1		*FRONT GRILLE	Not Necessary	312.80 FL	*- FL
3	1		*FRONT GRILLE LOGO	Not Necessary	68.55 FL	*- FL
4	1		*FRONT GRILLE CHROME MOULDING LOWER	Not Necessary	68.75 FL	*- FL
5	1		*FRONT GRILLE CHROME MOULDING TOP	Not Necessary	48.26 FL	*- FL
6	1		*FRONT BUMPER	Cut / Torn	552.90 FL	*552.90 FL
7	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	101.80 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP	Cracked	280.70 FL	*280.70 FL
9	1		*FRONT BUMPER FOG LAMP COVER	Cracked	56.07 FL	*56.07 FL
10	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	399.66 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINERS	Serviceable	99.68 FL	*- FL
12	1		*SET FRONT BUMPER CLIP	Necessary	35.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,954.67	1,739.77
- List Item Discount on L Items 25.00/25.00% (\$)	729.92	427.44
Total Parts (\$)	2,224.75	1,312.33

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO APPLY UNDERCOATING	New	100.00	0.00
3	PANEL BEATING	New	1,200.00	280.00
4	TO RESPRAY THE AFFECTED AREAS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,380.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >