

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400606
INV Date : 12-09-2024

Reference CD/FCI24070288/Ema3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMV 6229Z
Insured Veh. SHA 2511D
Claim No. D24006190MFCT/CTPL/ET
Policy No. D-24101861MFCT
Accident Date 13/07/2024
Inspection Date 19/07/2024

Description	Amount
Survey Inspection	250.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	250.00
GST (9%)	22.50
Grand Total	272.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD		Ref:	CD/FCI24070288/Ema3	
16 RAFFLES QUAY		Date:	12/09/2024	
#42-01 HONG LEONG BUILDING		Code:	FCI2	
SINGAPORE 048581				
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHA 2511D	Veh. Inspected	SMV 6229Z	
Policy No.	D-24101861MFCT	Coverage	0	
Claim No.	D24006190MFCT/CTPL/ET	Excess	\$0.00	
Assign From	EMILY TAN	Assign Date	17/07/2024	
2. Vehicle Details				
Make & Model	VOLVO S90 T5 MOMENTUM	C.C	1969	
Engine No.	B4204T231847940	Year of Reg.	29/12/2016	
Chassis No.	YV1PS10BDH1009826	Colour	WHITE	
Odometer	162531 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	255/35Z R20	CONTINENTAL	6	
L/H Front Tyre	255/35Z R20	CONTINENTAL	6	
R/H Rear Tyre	255/35Z R20	CONTINENTAL	6	
L/H Rear Tyre	255/35Z R20	CONTINENTAL	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/07/2024	Inspection Date	19/07/2024	
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMV 6229Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	TO REPAIR SEE LABOUR	\$2,300.00	\$0.00
1	FRONT BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	\$680.00	\$0.00
1	FRONT RIGHT HEADLAMP ASSY	CUT	\$3,850.00	\$3,850.00
1	FRONT BUMPER SENSOR (RH)	NOT NECESSARY	\$130.00	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$385.00)
			\$6,960.00	\$3,465.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REMOVE & REFIT HEADLAMP ASSY & SENSOR .INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER LOWER SPOILER.		\$1,200.00	\$250.00
	SPRAY PAINT FRONT RH FENDER FRONT BUMPER & LOWER SPOILER		\$900.00	\$500.00
	CHECK & TEST FOR PROPER FUNCTIONING FOR HEADLAMP & FRONT SENSOR		\$80.00	\$80.00
			\$2,180.00	\$830.00

GRAND TOTAL		\$9,140.00	\$4,295.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$3,450.00
Report Ref No: CD/FCI24070288/Ema3			

CTY

STEVE CHEN TSUE YEE


DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z





PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z



PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SMV 6229Z

