ASS. REG. BY: Taypin - 1 KEF: CS CT124070289 Tayp3

| ASS | IGNMENT |
|--|--|
| From: Date: | Veh No: CB7426M Yr Regn: 2014, 08 |
| OD TO IMO ITO DECLOSE | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover / |
| OD/TP/WS/TP RES/OD RES/EVA/INV/MV | Truck / Traller or |
| to maked MO: | Make: Toyota Coaster c.c 4009 |
| at Workshop m/s | Colour White AVC: Insured/Std/Ni/NA |
| 01 | Sp.Reading 66/539 T/Radio: Insured / Std / NI / NA |
| Insured: | Eng/No: |
| Policy No. | C/No: 376 FP 538003500682 |
| Claims No. | Gen. Cond: 60d / Fair / Poor / Burnt |
| | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inforder/Jammed/Leakod/Burnt or |
| Make of Veh; | Modl: (N) / S/Rim / STD A/Rim or |
| (District October 1985) | Tyre Size: F: 215 75 17.5 |
| (Policy Condition) Remark: The veh had commenced its N/S 0/S | R: (D) |
| repair at the time of inspection. | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR) SUMI / TOYO / YOKO or |
| Bal. or Market Value: \$66K | Front Rear |
| IDAC Accident Rport Consistent? : Yes or No | R/Bal. 6 mm R/Bal. 6/6 mm |
| GIA / PR Seen: Consistent?: Yes or No | L/Bal. L/Bal. L/Bal. L/Bal. mm |
| Est Repairs: days Res.: Yes or No | D.O.A. D.O.I. 18 4724 |
| Lum Sum: % 3 Val.: Yes or No | Survey held at Ding Ando Carros CA |
| | Des. of Damages Frt) Rear / O/S / N/S / U/C / Rooftop or |
| Date:Person Contacted: Vehicle: IN / OUT | The Tite I change in the second of the secon |
| Date / Time Action / Instruction | The U/C / Chassis frame / Body Structure affected due to collision. |
| | |
| | |
| | |
| | |
| | |
| | |
| | · · · · · · · · · · · · · · · · · · · |
| Date/Time, File Pass to? Prell. Report | ays Of Repair: |
| i) : Final Report | esurvey No. of Trip: Survey Fee: |
| Dale/Time, File Return to? | Transportation: |
| Add Fee: | : Site Insp (\$)s+Rssi |
| Star Same | : Interview (\$) Photos |
| Lump Sum/LEA: 15 | : Tech. Invs (\$) Others |
| | : Meel:eluci (iz |
| | TOTAL |

Ding Auto Pte Ltd Sin Ming Industrial Est. Sec C, Blk 10,#01-20 575645

Insurer Reference: CB7426M Repairer Reference: 071642

Date calculated: 17/07/2024 5:30 PM



Full Report Registration: CB7426M

Printed: 17/07/2024 5:30 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

China Taiping Insurance

(Singapore) Pte Ltd SGD

Printed by: Claim Reference:

Estimated Repair Time: Actual Repair Days:

Ding Auto CB7426M

Currency: Date of Incident:

Hire Car Start: Hire Car End:

04/07/24

Vehicle Details

Vehicle

Manufacturer:

Model:

PREPARE OFF VEHICLE

TOYOTA COASTER

Sub Model:

EX

Model Sheet Number:

70 S1 02

Registration:

CB7426M JTGFP538003500682

VIN number: Odometer:

Model Specs

FROM 05.2012

FOG LAMPS

4.0 LTR 75 KW

TWO COAT METALLIC

anjim 97495749/62563561 Unt M thorise Ex! \$2000 18/7/2484pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

All Underbody



Tyres Condition

Tyre Brand

Tread (Left Middle), Tread (Left Outer), Tread (Left Inner), Tread (Right Inner), Tread (Right Outer), Tread (Right

Condition

mm

mm

mm

Middle), mm

Spare Tyre Brand

Tread (Spare), mm

Labour

| Labour | Time Base 10 WU/h | Price = 42. | 00 SGD/h |
|-------------|---|-------------|-----------|
| Code | Description | WU | Price SGD |
| 520011 | R + R BUMPER | 3.0 | 12.60 |
| 520011 | R + R ATTACHED PARTS OF THE BUMPER | 6.0 | 25.20 |
| NO NUMBER | R + R L/BUMPER BRACKET | 1.0 | 4.20 |
| NO NUMBER | R + R R/BUMPER BRACKET | 1.0 | 4.20 |
| 751011 | R + R RADIATOR GRILLE | 2.0 | 8.40 |
| 810052 | R + R LEFT HEADLAMP | 6.0 | 25.20 |
| 810051 | R + R RIGHT HEADLAMP | 6.0 | 25.20 |
| NO NUMBER | ADJUST HEADLAMPS | 2.0 | 8.40 |
| NO NUMBER | REPLACE BONNET | 40.0 | 168.00 |
| B085 | R + R COWL PANEL TRIM | 2.0 | 8.40 |
| 851091 | R + R WASHER RESERVOIR | 4.0 | 16.80 |
| 051051 | INCLUDES: R + R RADIATOR EXPANSION TANK | | |
| NO NUMBER | R + R WIPER MOTOR | 1.0 | 4.20 |
| 850171) ZAX | R + R WIRE LINKAGE | 2.0 | 8.40 |
| NO NUMBER | RENEW FR/LWR CROSSMEMBER | 8.0 | 33.60 |
| NO NUMBER | RENEW CROSSMEMBER REINFORCEMENT | 13.0 | 54.60 |
| M180 | R + R STEERING COLUMN ASSY | 10.0 | 42.00 |
| 550351 | R + R INSTRUMENT PANEL TRIM | 23.0 | 96.60 |

| Description | | | WU | Price SGD |
|--|--|---|---|--|
| DENEW INSTRUMENT PANEL CROSSMEMBER | | | 7.0 | 29.40 |
| RENEW HEATER UNIT (REMOVED) | | | 1.0 | 4.20 |
| REMOVE AND REFIT WARM AIR HOUSING | | | | 42.00 |
| WINDSCREEN REMOVE AND REFIT | | | 20.0* | 84.00 |
| Labour Cost | | Hrs | WU | |
| Panel / Mechanical Labour | | 16.80 | 168.0 | 705.60 |
| Total of Labour | | | | 705.60 |
| | | | | |
| SYSTEM AZT | | Tir | ne Basis | 10 WU/h |
| Description - TWO COAT METALLIC | | | WU | Price SGD |
| BONNET NEW PART PAINTING | | | 21.0 | |
| | | | 4.0 | |
| CROSSMEMBER REINF SURFACE PAINT | | | 4.0 | |
| FRONT BUMPER NEW PART PAINT K1R | | | 14.0 | |
| Per Part | | | | |
| Description | | | | Price SGD |
| BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R | | î | | 67.60 3.74 4.73 71.34 |
| Labour Cost - Paint Factor | 42.00 SGD/h | Hrs | | |
| | | 2 50 | | |
| Preparation Main Work Metal | | | | |
| Total | 10 WU/h | | | |
| Material Cost - Paint New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Preparation Material-constant Plastic Total | | | | Price SGD 67.60 71.34 8.47 28.60 9.00 185.01 |
| | RENEW INSTRUMENT PANEL CROSSMEMBER RENEW HEATER UNIT (REMOVED) REMOVE AND REFIT WARM AIR HOUSING WINDSCREEN REMOVE AND REFIT Labour Cost Panel / Mechanical Labour Total of Labour SYSTEM AZT Description - TWO COAT METALLIC BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R Per Part Description BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R Labour Cost - Paint Freparation Main Work Metal Preparation Main Work Plastic Total Material Cost - Paint New Part Painting New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Preparation Material-constant Metal Preparation Material-constant Plastic | RENEW HEATER UNIT (REMOVED) REMOVE AND REFIT WARM AIR HOUSING WINDSCREEN REMOVE AND REFIT Labour Cost Panel / Mechanical Labour Total of Labour SYSTEM AZT Description - TWO COAT METALLIC BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R Per Part Description BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT K1R Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Comp. Work Plastic Total Material Cost - Paint New Part Painting New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Preparation Material-constant Metal Preparation Material-constant Metal Preparation Material-constant Metal Preparation Material-constant Plastic | RENEW INSTRUMENT PANEL CROSSMEMBER RENEW HEATER UNIT (REMOVED) REMOVE AND REFIT WARM AIR HOUSING WINDSCREEN REMOVE AND REFIT Labour Cost Panel / Mechanical Labour Total of Labour SYSTEM AZT Description - TWO COAT METALLIC BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT KIR Per Part Description BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT KIR Per Part Description BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINT KIR Labour Cost - Paint Factor Time Paint Preparation Main Work Metal Preparation Main Work Metal Preparation Comp. Work Plastic Total Material Cost - Paint New Part Painting - Plastic KIR Surface-/Blend Paint Material-constant Metal Preparation Material-constant Metal Preparation Material-constant Plastic | RENEW INSTRUMENT PANEL CROSSMEMBER RENEW HEATER UNIT (REMOVED) REMOVE AND REFIT WARM AIR HOUSING WINDSCREEN REMOVE AND REFIT Labour Cost Panel / Mechanical Labour SYSTEM AZT Time Basis Description - TWO COAT METALLIC BONNET NEW PART PAINTING FRONT CROSSMEMBER SURFACE PAINT CROSSMEMBER REINF SURFACE PAINT FRONT BUMPER NEW PART PAINTING FRONT BUMPER NEW PART PAINTING BONNET NEW PART PAINTING FRONT BUMPER NEW PART PAINT K1R Per Part Description BONNET NEW PART PAINTING FRONT BUMPER NEW PART PAINT K1R Labour Cost - Paint FRONT BUMPER NEW PART PAINT K1R Labour Cost - Paint FRONT BUMPER NEW PART PAINT K1R Labour Cost - Paint Preparation Main Work Metal Preparation Comp. Work Plastic Total Material Cost - Paint New Part Painting New Part Painting - Plastic K1R Surface-/Blend Paint New Part Painting - Plastic K1R Surface-/Blend Paint Material-constant Metal Preparation Material-constant Plastic |

Spare Parts

| Code | Description | Part Number | Part Source | prices as at 2015-06-01/01 Price SGD |
|------|---------------|-------------|-------------|---|
| 1004 | AIRCON BLOWER | - | Original | 2,800.00 |
| 0471 | BONNET | 53301 0S010 | Original | 4,980.00 |
| 0431 | BONNET BADGE | 75315 36030 | Original | 130.00 |
| 1001 | CONDENSER | - | Original | 10,070.00 |

| 1324 | Code | Description | Part Number | Part Source | | Price SGD |
|--|-------------------|----------------------|-------------|-------------|-----------|---------------|
| O281 | | | | | | |
| 1019 | | | | | di | 2 2.080.00 |
| 1413 | | | | | | 1.980.00 |
| OA10 | | | | Original | M | 0.00 |
| HEATER BLOWER 87110 36730 Original 0,800.00 | | | | Original | cue | 1 060 00 |
| 1000 | | | | | | |
| 125.00 1 | | | | | | <i>C</i> / |
| Description | | | | | | |
| 0635 | | | | | ſ | |
| 1453 | | various and a second | | | · | |
| 1445 | | | | | | 7 125 00 |
| OS61 | | | | | | 7 1 740 00 |
| 0.280 | | | | | con | 2 095 00 |
| 0.254 | | | | | | |
| 0636 | | | | | | |
| 1454 | | | | | | |
| 1446 | | | | | | |
| 1002 | | | | | | |
| 1003 | | | | | | |
| Non-OEM Parts Savings Subtotal State | | 5 5 | _ | | | 71 |
| 1436 | | | 91110 36471 | | C | (a) ~2 005 00 |
| 1411 | | | | | • | 2,093.00 |
| 1410 | | | | Original | | |
| 1461 | | | | Original | i i | |
| ## 1450 WIPER MOTOR ## 1450 Original ## 1650.00 ## 16 | | | | | ı | |
| Savings Subtotal | | | | | | |
| Subtotal Subtotal St,682.00 | 1.150 | WITER MOTOR | 03070 03010 | Original | | (030.00 |
| Subtotal S1,682.00 Total S1,682.00 | f: OEM Parts | Savings | | | | 0.00 |
| Total 51,682.00 Final Calculation SGD SGD Parts 51,682.00 Total Parts 51,682.00 Labour Time Base 10 WU/h 705.60 Total 168.0 WU X 42.00 SGD/h 705.60 Paint Work Time Base 10 WU/h 306.60 Material Cost 73.0 WU X 42.00 SGD/h 306.60 Material Cost Total Paint Including Material 491.61 Repair Cost Excludes GST 52,879.21 GST (+9.00%) 4,759.13 | n: Non-OEM Parts | | | | | |
| Parts 51,682.00 SGD SGD | u: Used parts | | | | | J-/002.00 |
| Parts 51,682.00 | | Total | | | | 51,682.00 |
| Parts Total Parts 51,682.00 Labour Time Base 10 WU/h Total 168.0 WU X 42.00 SGD/h Total of Labour 705.60 Paint Work Time Base 10 WU/h Labour Cost 73.0 WU X 42.00 SGD/h Material Cost Total Paint Including Material 306.60 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST | Final Calculati | ion | | | | |
| Total Parts 51,682.00 Labour Time Base 10 WU/h | | | | | SGD | SGD |
| Total Parts 51,682.00 Labour Time Base 10 WU/h | Parts | | | | 51,682,00 | |
| Labour Time Base 10 WU/h 705.60 Total 168.0 WU X 42.00 SGD/h 705.60 Paint Work Time Base 10 WU/h Labour Cost 73.0 WU X 42.00 SGD/h 306.60 Material Cost 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST GST (+9.00%) 4,759.13 | | | | | 31,002.00 | 51,682,00 |
| Total 168.0 WU X 42.00 SGD/h Total of Labour Paint Work Time Base 10 WU/h Labour Cost 73.0 WU X 42.00 SGD/h Material Cost Total Paint Including Material Repair Cost Excludes GST GST (+9.00%) Repair Cost Included CST 705.60 705.60 491.61 | | | | | | , |
| Total of Labour 705.60 Paint Work Time Base 10 WU/h Labour Cost 73.0 WU X 42.00 SGD/h Material Cost 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST 52,879.21 GST (+9.00%) Repair Cost Included CST | | | | | | |
| Paint Work Time Base 10 WU/h Labour Cost 73.0 WU X 42.00 SGD/h 306.60 Material Cost 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST 52,879.21 GST (+9.00%) 4,759.13 | | J X 42.00 SGD/h | | | 705.60 | |
| Labour Cost 73.0 WU X 42.00 SGD/h 306.60 Material Cost 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST 52,879.21 GST (+9.00%) 4,759.13 | Total of Labour | | | | | 705.60 |
| Labour Cost 73.0 WU X 42.00 SGD/h 306.60 Material Cost 185.01 Total Paint Including Material 491.61 Repair Cost Excludes GST 52,879.21 GST (+9.00%) 4,759.13 | Paint Work Time | e Base 10 WU/h | | | | |
| Material Cost Total Paint Including Material Repair Cost Excludes GST GST (+9.00%) Repair Cost Included CST 491.61 | | | | | 306.60 | |
| Total Paint Including Material Repair Cost Excludes GST GST (+9.00%) Repair Cost Included GST 491.61 | | | | | | |
| Repair Cost Excludes GST 52,879.21 GST (+9.00%) 4,759.13 | | ding Material | | | 103.01 | 404.64 |
| GST (+9.00%) 4,759.13 | , will allold | | | | | 491.61 |
| GST (+9.00%) A,759.13 | | des GST | | | | 52,879.21 |
| | | | | | | |
| | Repair Cost Inclu | ded GST | | | | |

Comments

* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

04/07/2024 17:58 (SGT) Date of First Submission Actual Driver 04/07/2024 09:15 (SGT) Date of Accident Jurong West Ave 5, Singapore Exact Location of Accident Additional Location Information Country/State of Loss

DETAILS OF OWN VEHICLE

Vehicle Registration Number CB7426M

INSURED/POLICYHOLDER

Is company? JOSEPH COACH PTE LTD Name Of Registered Owner 201719851E Company Reg No josephcoachsg@gmail.com Email Address (Phone) +65-91781988 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Toyota Manufacturer Coaster Model 19 SEATER MANUAL TURBO ABS Variant

Exact purpose for which vehicle was being used at time of Employment

Are you claiming under your own insurance policy for repair to No - Reporting only your vehicle? Vehicle Category

Transmission Manual 4009 CC

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMB1SNW00010632304

DRIVER

Name of Driver LIM CHEE KEONG NRIC No S1756502H Date Of Birth 09/09/1966 Occupation Outdoor

| Driving Pass Date Driving experience Gender | 15/07/1996 28 YEARS Male |
|--|--|
| GC1155 | (Phone) +65-98933222 |
| Mobile Number | (Filalie) 100 00000222 |
| Alt. Phone Number | |
| Email Address | josephcoachsg@gmail.com |
| Address | BLK 679 CHOA CHU KANG CRESCENT #06-584 |
| Address complement | ÷ |
| Postcode | 680679 |
| Is the driver the policyholder? | No |
| If No. Relationship of the Driver with the Insured | Employee |
| | the state of the s |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | |
| The state of the s | * |
| Insurance Company of Other Vehicle Owned by Driver | - - |
| GENERAL INFORMATION OF THE ACCIDENT | |
| Type of Accident | Chain Collision |
| | |
| Weather Conditions | |
| Road Surface | Dry |
| OTHER INFORMATION | |
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | |
| | |
| Was anybody injured in the Accident? | |
| Was any injured conveyed to hospital by ambulance? | • |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 4 |
| Has the driver been approached by unknown person(s) | |
| soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator S fidille | |
| Translator's ID | |
| Translator's phone number | |
| Translator's email | |
| Original language used in the statement | <u>₩</u> |
| | |
| PASSENGER 1 | |
| Namo | Passenger |
| Name | |
| Gender | Mule |
| | |
| PASSENGER 2 | |
| Name | Passenger |
| | |
| Gender | Wale |
| PASSENGER 3 | |
| Name | Passenger |
| 140.110 | Male |
| Gender | Wale |
| DETAIL O OF DOLLOT ACTION | |
| DETAILS OF POLICE ACTION | |
| Was the accident reported to the police? | Yes |
| Was the accident reported to the panel | |
| Police Station Name | Jurong Division Headquarters |
| Police Station Phone No | A |
| Alt. Police Station Phone No | (Fax) +65-68965647 |
| Police Station Address | No. 2 Jurong West Avenue 5 Singapore 649482 |
| | |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |
| | |

CIRCUMSTANCES OF ACCIDENT

REFER TO THE ATTACHED POLICE REPORT

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

| Vehicle Registration Number | *>- × | SHB6270S |
|---|-------|----------|
| Vehicle Manufacturer | | * |
| Vehicle Model | | - |
| Vehicle Variant | | - |
| Vehicle Colour | | - |
| Vehicle Category | | Taxi |
| Name of Driver | | = |
| Contact Number | 11+ | ¥ |
| Address | *** 1 | • |
| Address complement | | • |
| Postcode / | | _ |
| Insurance Company Name | | = |
| Nature Of Damage | | - |
| Details of property damaged in accident | | |
| No. Of Passenger (Including Driver) | r. 16 | |
| | | |

DETAILS OF OTHER VEHICLE PROPERTY 2

| Vehicle Registration Number | SHB7670P |
|---|----------|
| Vehicle Manufacturer | _ |
| Vehicle Model | - |
| Vehicle Variant | = |
| Vehicle Colour | ** |
| Vehicle Category | Taxi |
| Name of Driver | - |
| Contact Number | - |
| Address | _ |
| Address complement | _ |
| Postcode | _ |
| Insurance Company Name | _ |
| Nature Of Damage | _ |
| Details of property damaged in accident | _ |
| No. Of Passenger (Including Driver) | 1 |
| no. or accorded (moreoning briver) | , |

SKETCH PLAN

IMPORTANT NOTICE

- 1. Presse report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Actual Other
- 3 information provided must be an <u>invinity</u> and accusate as possible. Any withit misrepresentation or withholding of material fauls may allow eventance companies to GONDARE TOPOL repets
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for Investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre epiblished by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8 Consent under the Personal Data Protection Act (PDPA)

I understand acknowledge agree and consent that

(a) My insurer my workshop and the General Insurance Association of Singapore ("CIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers' law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the clasms,


- (ii) investigating the accident and/or my claims.
- (*) carrying out and/or dealing with my instructions or responding to any enquiries by me
- (iv) administering my claims (including the mailing of correspondence statements, invoices reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mad packages), and/or
- (v) complying with applicable law in administering processing handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers' aw firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or openits (uncluding their lawyers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes

Poicholder's Synature / Di

Drivers Signshire (if droot is not the policyholder) / Date

Witnessed by Reporting Conta Forsonnel (Name as in NRICH) card)

Sketch Plan



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | ~ |
|-------------------------------|------------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 851E |
| Vehicle Details | |
| Vehicle No.: | CB7426M |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 18 Jul 2024 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | COASTER 19 SEATER MANUAL TURBO ABS |
| Primary Colour: | White |
| Manufacturing Year: | 2014 |
| Engine No.: | N04CUH17582 |
| Chassis No.: | JTGFP538003500682 |
| Maximum Power Output: | |
| Open Market Value: | \$73,852.00 |
| Original Registration Date: | 04 Aug 2014 |
| First Registration Date: | 04 Aug 2014 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$3,693.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Rebate Amount: | \$0.00 |
| Total Rebate Amount: | \$0.00 |
| Message | |

The information contained herein is correct as at 18 Jul 2024