



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO AQ 88X(FBW5145M)

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	FORK INNER TUBES	N/S BENT	\$440.00	\$180.00
2	FORK OUTER TUBER	N/S DAMAGED	\$450.00	\$225.00
1	FORK UNDER BRACKET	SERVICEABLE	\$220.00	\$0.00
1	FRONT SPORT RIM	NOT NECESSARY	\$480.00	\$0.00
1	FRONT RIM SHAFT	NOT NECESSARY	\$98.00	\$0.00
1	FRONT RIM BEARING	NOT NECESSARY	\$88.00	\$0.00
1	SET SIDE MIRROR	CUT	\$145.00	\$80.00
1	HANDLE-BAR	BENT	\$225.00	\$160.00
1	SET HANDLE-BAR ENDS	CUT	\$128.00	\$40.00
1	SET HAND GRIP	NOT NECESSARY	\$100.00	\$0.00
1	FRONT FOOTREST BRACKET	BENT	\$230.00	\$118.00
1	FRONT FOOTREST RUBBERS N/S	TORN	\$90.00	\$48.00
1	GEAR PEDAL	BENT	\$120.00	\$120.00
1	REAR FOOTREST	SERVICEABLE	\$142.00	\$0.00
1	REAR FOOTREST BRACKET	SERVICEABLE	\$275.00	\$0.00
1	MAIN STAND	NOT NECESSARY	\$135.00	\$0.00
1	SIDE STAND	NOT NECESSARY	\$105.00	\$0.00
1	SET FAIRING ASSY	CRACKED	\$680.00	\$680.00
	LESS 10.00% DISCOUNT		(\$415.10)	(\$165.10)
			\$3,735.90	\$1,485.90
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET NUMBER PLATE (SN)	NOT NECESSARY	\$38.00	\$0.00
2	FORK OILS (SN)	NECESSARY	\$30.00	\$10.00
2	FORK OIL SEALS (SN)	NECESSARY	\$56.00	\$20.00
1	SET STEERING CONE (SN)	NOT NECESSARY	\$120.00	\$0.00
1	REAR BOX (SN)	CUT	\$480.00	\$300.00
1	REAR BOX BRACKET (SN)	BENT	\$180.00	\$150.00
1	SET STICKER (SN)	NOT NECESSARY	\$120.00	\$0.00
			\$1,024.00	\$480.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	NOT NECESSARY	\$80.00	\$0.00
	TO REPAIR BODY FRAME	NOT NECESSARY	\$480.00	\$0.00
	TO PROVIDE LABOUR		\$420.00	\$300.00
			\$980.00	\$300.00
GRAND TOTAL			\$5,739.90	\$2,265.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,800.00
Report Ref No: CS/INC24070290/Uvh3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.