

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24070297/UVP3M4**Date:** 26/08/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** XD5840D **Insured Vehicle No :** GBL4568R

Date of Loss: 12/07/2024 Nature of Claim: TP Claim No: DMCF2400030H/02/AF

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD5840D**

Make & Model: MITSUBISHI FV51JP4RDEA, 12.9 D (M) Engine No: 6M70449757

Reg. Date: 04/04/2012 (Man. Year: 2011) Chassis No: FV51JPA00671

Colour: White Odometer: 363191 km

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5 (D/D)

Front Left Side: MAX WIND 5 mm Rear Left Side: Meallir 5/5/5/5 mm

Front Right Side: MAX WIND 5 mm Rear Right Side: Meallir 5/5/5/5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,218.51	4,539.74	9,678.77	68.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,150.00	1,720.00	2,430.00	58.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,368.51</b>	<b>6,259.74</b>	<b>12,108.77</b>	<b>65.92</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>(S\$)</b>	18,368.51	5,000.00	13,368.51	72.78
<b>+ GST 9.00/9.00% (S\$)</b>	1,653.17	450.00	1,203.17	72.78
<b>Nett Amount (S\$)</b>	<b>20,021.68</b>	<b>5,450.00</b>	<b>14,571.68</b>	<b>72.78</b>

INSPECTION

Date of Assignment: 18/07/2024

Date Inspected: 22/07/2024 Inspected At: 1ST AUTOMOTIVE SERVICES PTE LTD  
53 UBI AVENUE 1 #01-23 PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408934

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Aug 2024)	
Parts:	N/A	mitsubishi FV51JP4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD5840D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Repair	6,995.60 FL	*- FL
2	1		*FRONT RH DOOR OUTER GARNISH	No such part	880.40 FL	*- FL
3	1		*FRONT DOOR SIGNAL LAMP RH	Broken/Missing	231.60 FL	*231.60 FL
4	1		*FRONT BUMPER	Distorted	1,993.87 FL	*1,993.87 FL
5	1		*FRONT BUMPER CENTER GARNISH RH	Not Necessary	295.51 FL	*- FL
6	1		*FRONT BUMPER RH FOGLAMP	Not Necessary	299.34 FL	*- FL
7	1		*FRONT BUMPER RH FOGLAMP COVER	Twisted	197.25 FL	*197.25 FL
8	1		*FRONT BUMPER SIDE GARNISH RH	Distorted	190.84 FL	*190.84 FL
9	1		*FRONT BUMPER TOP GARNISH (BLACK)	Not Necessary	98.41 FL	*- FL
10	1		*FRONT RH CORNER GARNISH SIGNAL LAMP	Not Necessary	227.91 FL	*- FL
11	1		*FRONT RH HEADLAMP	Not Necessary	1,389.44 FL	*- FL
12	1		*FRONT RH HEADLAMP BRACKET	Not Necessary	935.64 FL	*- FL
13	1		*FRONT RH HEADLAMP COVER	Twisted	305.00 FL	*190.84 FL
14	1		*FRONT RH STEP GARNISH (LOWER)	Broken	795.63 FL	*795.63 FL
15	1		*FRONT RH STEP GARNISH (LOWER) STEEL PLATE	Broken	366.60 FL	*366.60 FL
16	1		*FRONT RH STEP GARNISH (TOP)	Cracked	355.27 FL	*355.27 FL
17	1		*FRONT RH STEP GARNISH (TOP) STEEL PLATE	Repair	326.60 FL	*- FL
18	1		*FRONT RH STEP GARNISH BRACKET (FRONT)	Not Necessary	971.96 FL	*- FL
19	1		*FRONT RH STEP GARNISH BRACKET (REAR)	Bent	699.25 FL	*480.00 FL
20	1		*FRONT RH CORNER GARNISH	Cut/Cracked	1,251.09 FL	*1,251.09 FL
21	1		*FRONT RH CORNER GARNISH BRACKET	Not Necessary	150.80 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	18,958.01	6,052.99
- List Item Discount on L Items 25.00/25.00% (S\$)	4,739.50	1,513.25
Total Parts (S\$)	14,218.51	4,539.74

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING (TO FR)	New	100.00	20.00
2	TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,500.00	800.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,000.00	900.00
4	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	150.00	0.00
5	APPLY ANTI RUST CHEMICAL	New	200.00	0.00
6	TRANSFER TO DOOR	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,150.00</b>	<b>1,720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >