

ASSIGNMENT

From: _____ Date: _____
 Estin: _____
 OD / TP / RES / OD RES / EVA / INV / MV
 To In: _____ Vehicle No: _____
 at W: _____ m/s
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____
 (Policy Condition)

Remark: Vch had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GQ2888U Yr Regn: 2017, Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Nissan Cabstar C/D 2953

Colour: Gold A/C: Insured / Std / NI / NA

Sp. Reading: 87472 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNISC2F24Z0859201

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195R15C Rolevo

R: 155R13C Windforce

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 18/07/24

Survey held at Twin Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP III</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No (✓)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>3952.</u>

Date/Time, File Pass to?

☐ : Preli. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Report Form: A.P. P. C.

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

FENG YI CONSTRUCTION PTE LTD
694 JURONG WEST CENTRAL 1 #01-09
SINGAPORE 640694

Contact : 91456763 90854868

TAX INVOICE

Repair Code : CLM16363
Date in : 18/07/2024
Vehicle Num. : GQ2888U
Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Chassis/Eng# : JN1SC2F24Z0859201/ZD30014834N

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR END PANEL <i>Repair</i>	1	326.00	+ 326.00
REAR END SIDE BRACKET L/R <i>new</i>	2	105.00	+ 210.00
REAR END SIDE BRACKET RUBBER STOPPER L/R <i>new</i>	4	20.00	+ 80.00
REAR NUMBER PLATE BRACKET <i>new</i>	1	75.70	+ 75.70
REAR NUMBER PLATE LAMP <i>new</i>	1	53.50	+ 53.50
REAR SPARE TYRE CARRIAGE <i>new</i>	1	209.40	+ 209.40
REAR TAILGATE <i>Dented</i>	1	1459.60	- 1,459.60
REAR TAILGATE HINGES <i>new</i>	3	27.30	+ 81.90
REAR TAILGATE SIDE LOCK L/R <i>new</i>	2	182.90	+ 365.80
REAR TAILLAMP ASSY L/R <i>new</i>	2	206.70	+ 413.40
REAR TAILLAMP BRACKET L/R <i>new</i>	2	65.00	+ 130.00
Subtotal before discount			3,405.30
Percentage discount 10%			340.53
Sub-total 1			3,064.77
REAR FLOOR PANEL TOP STEEL PLATE <i>new</i>	1	1600.00	+ 1,600.00
REAR FLOOR PANEL TOP STEEL PLATE RIVET - SET <i>new</i>	1	100.00	+ 100.00
REAR NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
REAR REVERSE SENSOR - SET <i>new</i>	1	280.00	+ 280.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

FENG YI CONSTRUCTION PTE LTD
694 JURONG WEST CENTRAL 1 #01-09
SINGAPORE 640694

Contact : 91456763 90854868

TAX INVOICE

Repair Code : CLM16363

Date in : 18/07/2024

Vehicle Num. : GQ2888U

Model : NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Chassis/Eng# : JN1SC2F24Z0859201/ZD30014834N

REAR STEP BRACKET (STEEL) <i>Bert</i>	1	350.00	<i>120</i> 350.00
REAR TAILGATE '13PAX' STICKER <i>2 per</i>	1	25.00	<i>15</i> 25.00
REAR TAILGATE '70KM' STICKER	1	25.00	<i>15</i> 25.00
REAR TAILGATE HINGES PIC & NUT - SET <i>2 w</i>	3	25.00	<i>4</i> 75.00
REAR TAILGATE INNER STEEL PLATE <i>Bert</i>	1	1000.00	<i>380</i> 1,000.00
REAR TAILGATE INNER STEEL PLATE RIVET - SET <i>w</i>	1	100.00	<i>40</i> 100.00
Subtotal before discount			3,580.00
Percentage discount 0%			0.00
Sub-total 2			3,580.00
Parts-total			6,644.77

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor. ✓ 80.00
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR) X 80.00
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. *400* ~~800.00~~
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. *3w* ~~700.00~~
- To apply anti-rust chemical on repaired and replaced panel. *40* ~~80.00~~

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature. ***

Labour Total
Parts & Labour Total

1,740.00
8,384.77

Acknowledged by Repairer
Signature:
Date:

page 2

Adrian Lj
1/2 18/07/24
04 Days.