

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24070303/UNP3E2**Date:** 12/08/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001404261	
<b>Claimant Vehicle No :</b>	SMM6063G	<b>Insured Vehicle No :</b>	SLQ1268G	
Date of Loss:	18/07/2024	Nature of Claim:	TP	Claim No: 367496

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMM6063G</b>	Engine No:	2ZR0C29548
Make & Model:	TOYOTA NOAH HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR800342759
Reg. Date:	05/07/2019 (Man. Year: 2018)	Odometer:	189071 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Goodride 7 mm	Rear Left Side:	Goodride 7 mm
Front Right Side:	Goodride 7 mm	Rear Right Side:	Goodride 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,361.56	4,342.71	10,018.85	69.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	1,710.00	1,930.00	53.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>18,001.56</b>	<b>6,052.71</b>	<b>11,948.85</b>	<b>66.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>(S\$)</b>	18,001.56	4,800.00	13,201.56	73.34
<b>+ GST 9.00/9.00% (S\$)</b>	1,620.14	432.00	1,188.14	73.34
<b>Nett Amount (S\$)</b>	<b>19,621.70</b>	<b>5,232.00</b>	<b>14,389.70</b>	<b>73.34</b>

INSPECTION

Date of Assignment:	22/07/2024		
Date Inspected:	22/07/2024	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Aug 2024)
Parts:	M1-MPV	TOYOTA NOAH HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6063G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN	Not Necessary	1,655.10 F	*- FL
2	1	*REAR WINDSCREEN MOULDING	No such part	185.50 F	*- FL
3	1	*TAILGATE	Dented / Bent	2,994.45 F	*1,985.90 FL
4	1	*TAILGATE OUTER CHROME GARNISH	Not Necessary	688.10 F	*- FL
5	1	*TAILGATE EMBLEM HYBRID	Necessary	68.90 F	*68.90 FL
6	1	*TAILGATE INNER LOCK	Damaged	609.23 F	*409.90 FL
7	1	*TAILGATE INNER TRIM BOARD	Deformed / Cracked	681.20 F	*681.20 FL
8	1	*TAILGATE INNER PULL GARNISH	Not Necessary	65.20 F	*- FL
9	1	*TAILGATE WEATHERSTRIP	Twisted	399.45 F	*399.45 FL
10	1	*TAILGATE KEYLESS SMART	Serviceable	185.30 F	*- FL
11	1	*REAR BUMPER	Dented / Deformed	1,655.10 F	*985.10 FL
12	2	*REAR BUMPER REFLECTORS	Not Necessary	290.00 F	*- FL
13	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	210.20 F	*- FL
14	1	*REAR END PANEL	Dented / Bent	955.23 F	*801.10 FL
15	1	*REAR END PANEL TOP GARNISH	Twisted	366.10 F	*285.40 FL
16	2	*TAILLAMP LOWER APRON GARNISHS	Not Necessary	770.20 F	*- FL
17	1	*REAR FLOOR PANEL	Repair	820.10 F	*- FL
18	1	*REAR FLOOR PANEL TOP BOARD (CRACKED)	Not Consistent With The Impact	1,282.20 F	*- FL
19	1	*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
20	1	*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
21	1	*REAR LICENCE PLATE	Not Necessary	50.00 FS	*- FS
22	1	*SET REAR BUMPER LOWER REFLECTIVE STICKER	Not Necessary	180.00 FS	*- FS
23	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
24	1	*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
25	1	*REAR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,361.56	5,746.95
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,404.24
Total Parts (\$\$)	14,361.56	4,342.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
3	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	60.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	50.00
6	TO RESET & REPROGRAMME SYSTEM	New	120.00	0.00
7	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>3,640.00</b>	<b>1,710.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >