

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24070304/AVP3E2**Date:** 30/08/2024**REFERENCE**

Insured/Claimant: WONG JUN MING (HUANG JUNMING)

Policy No: 7210081351

Date of Loss: 04/07/2024

Nature of Claim: OD

Claim No: 2458967628SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SNA9896B**

Make &amp; Model: AUDI A4, 2.0 TFSI S-TRONIC (A)

Engine No: DEM028960

Reg. Date: 27/07/2021 (Man. Year: 2020)

Chassis No: WAUZZZF47MA025311

Colour: Black

Odometer: 33551 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$146,000.00

Price:

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/50 R17

Rear Tyre Size: 225/50 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	33,885.00	15,706.32	18,178.68	53.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,572.00	3,122.00	2,450.00	43.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>39,457.00</b>	<b>18,828.32</b>	<b>20,628.68</b>	<b>52.28</b>
<b>- Excess (\$\$)</b>	<b>1,100.00</b>	<b>1,100.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>38,357.00</b>	<b>17,728.32</b>	<b>20,628.68</b>	<b>53.78</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	<b>3,452.13</b>	<b>1,595.55</b>	<b>1,856.58</b>	<b>53.78</b>
<b>Nett Amount (\$\$)</b>	<b>41,809.13</b>	<b>19,323.87</b>	<b>22,485.26</b>	<b>53.78</b>

**INSPECTION**

Date of Assignment: 19/07/2024

Date Inspected: 24/07/2024

Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 4.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,670.00 FS	*2,136.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	420.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	90.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	245.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	329.00 FS	-
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	176.00 FS	*- FS
7	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Cracked	329.00 FS	*262.80 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	338.00 FS	*- FS
9	1		*RADIATOR GRILLE	Cracked	1,949.00 FS	*1,559.20 FS
10	1		*CAUTION STICKER	Necessary	25.00 FS	*19.44 FS
11	1		*A/C STICKER	Necessary	10.00 FS	*7.52 FS
12	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	92.00 FS	*- FS
13	1		*FRONT BUMPER TOP BRACKET	Cracked	173.00 FS	*138.00 FS
14	1		*FRONT FOAM FILLER PIECE	Cracked	237.00 FS	*189.60 FS
15	1		*FRONT REINFORCEMENT BEAM	Dented	1,033.00 FS	*826.40 FS
16	2		*FRONT BUMPER TOP BRACKET SUPPORT - LH / RH	Damaged	74.00 FS	*57.76 FS
17	1		*LED HEADLIGHT - LH / RH	N/S Cracked	18,408.00 FS	*7,363.20 FS
18	3		*LED HEADLIGHT SPACER - LH / RH	Not Necessary	150.00 FS	*- FS
19	2		*LIFT CYLINDER - LH / RH	Not Necessary	504.00 FS	*- FS
20	2		*LIFT CYLINDER BRACKET - LH / RH	Not Necessary	16.00 FS	*- FS
21	1		*LIFT CYLINDER HOSE	Not Necessary	118.00 FS	*- FS
22	2		*HEADLIGHT TOP COVER - LH / RH	N/S Deformed	110.00 FS	*43.44 FS
23	1		*BONNET	Dented	3,470.00 FS	*2,776.00 FS
24	1		*BONNET ATTACHMENT PARTS	Not Necessary	460.00 FS	*- FS
25	2		*BONNET HINGE - LH / RH	Not Necessary	744.00 FS	*- FS
26	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	36.00 FS	*28.40 FS
27	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	70.00 FS	*56.80 FS
28	2		*BONNET STRIKER - LH / RH	Not Necessary	126.00 FS	*- FS
29	2		*BONNET LID LOCK - LH / RH	Not Necessary	491.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	71.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE	Not Necessary	71.00 FS	*- FS
32	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
33	1		*SUNDRIES	Necessary	600.00 FS	*30.16 FS
34	1		*FRONT BUMPER TOP COVER (Supplementary)	Deformed	160.00 FS	*127.60 FS
35	1		*OUTER TEMPERATURE SENSOR BRACKET (Supplementary)	Necessary	30.00 FS	*24.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **33,885.00**    **15,706.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE	New	700.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (\$)</b>			<b>5,572.00</b>	<b>3,122.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >