

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24070310/AQP3E2
Date: 17/10/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	GBF3605E	Insured Vehicle No :	GBM1699K
Date of Loss:	17/07/2024	Nature of Claim:	TP
		Claim No:	DMCV2400145H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3605E	Engine No:	1KD2605553
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2010194258
Reg. Date:	13/09/2016 (Man. Year: 2016)	Odometer:	180752 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Arivo 6 mm	Rear Left Side:	Arivo 6 mm
Front Right Side:	Arivo 6 mm	Rear Right Side:	Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,551.80	2,823.65	2,728.15	49.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,500.00	1,030.00	40.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,081.80	4,323.65	3,758.15	46.50
Approved Total (Overridden) (S\$)		3,400.00		
(S\$)	8,081.80	3,400.00	4,681.80	57.93
+ GST 9.00/9.00% (S\$)	727.36	306.00	421.36	57.93
Nett Amount (S\$)	8,809.16	3,706.00	5,103.16	57.93

INSPECTION

Date of Assignment:	18/07/2024	
Date Inspected:	19/07/2024	Inspected At: N-51 Automotive Pte Ltd (HQ) Kaki Bukit Autohub, 2 Kaki Bukit Ave 2 #01-18 Singapore 417921
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 17 Oct 2024)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3605E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH FENDER	Dented	2,315.40 FL	*2,105.00 FL
2	1		*REAR LH FENDER INNER PANEL	Repair	401.90 FL	*- FL
3	2		*REAR LH FENDER INNER VERTICAL PANEL	Dented	1,753.00 FL	*175.20 FL
4	1		*REAR LH SLIDING DOOR RAIL	Bent	700.60 FL	*580.00 FL
5	1		*REAR LH SLIDING DOOR RAIL COVER	Not Necessary	54.10 FL	*- FL
6	1		*REAR LH TAILLAMP	Cracked	458.10 FL	*398.00 FL
7	1		*REAR LH TAILLAMP INNER PANEL	Repair	771.60 FL	*- FL
8	1		*REAR LH TAILLAMP LOWER GARNISH	Not Necessary	127.70 FL	*- FL
9	1		*REAR LH FENDER ARCH GARNISH	Cracked	400.00 FS	*300.00 FS
10	1		*REAR LH FENDER WINDOW GLASS SEAL	Necessary	80.00 FS	*40.00 FS
11	1		*REAR LH FENDER WINDOW GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
12	1		*SET REAR LH TAILLAMP CLIPS	Not Necessary	30.00 FS	*- FS
13	1		*SET REAR LH TAILLAMP LOWER GARNISH CLIPS	Not Necessary	25.00 FS	*- FS
					<hr/>	
					Sub Total (\$\$)	7,197.40 3,638.20
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,645.60 814.55
					<hr/>	
					Total Parts (\$\$)	5,551.80 2,823.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	0.00
2	TO REMOVE, REINSTALL FENDER GLASS	New	150.00	80.00
3	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	80.00	60.00
4	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	600.00
5	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	700.00
6	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (S\$)			2,530.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >