

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP ECICS.
Xiao Chen

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-08 WIN 5
SINGAPORE 768091

TAX INVOICE

Repair Code : CLM16364

Date in : 18/07/2024

Vehicle Num. : GBF3605E

Model : TOYOTA HIACE DX 3.0 MANUAL

Chassis/Eng# : KDH2010194258/1KD2605553

Contact : 94888856 98628321

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR LH FENDER <i>Dented</i>	1	2315.40	2315.40 2105
REAR LH FENDER INNER PANEL <i>Repair</i>	1	401.90	401.90
REAR LH FENDER INNER VERTICAL PANEL <i>Dented</i>	2	876.50 87.60x2	1753.00 175.20 ✓
REAR LH SLIDING DOOR RAIL <i>Best</i>	1	700.60	700.60 580
REAR LH SLIDING DOOR RAIL COVER <i>Ken</i>	1	54.10	54.10
REAR LH TAILLAMP <i>Cracked</i>	1	458.10	458.10 398
REAR LH TAILLAMP INNER PANEL <i>Repair</i>	1	771.60	771.60
REAR LH TAILLAMP LOWER GARNISH <i>Ken</i>	1	127.70	127.70
Subtotal before discount			6,582.40
Percentage discount 25%			1,645.60
Sub-total 1			4,936.80
REAR LH FENDER ARCH GARNISH <i>Cracked</i>	1	400.00	400.00 300
REAR LH FENDER WINDOW GLASS SEAL <i>Ken</i>	1	80.00	80.00
REAR LH FENDER WINDOW GLASS SEALANT <i>Ken</i>	1	80.00	80.00
REAR LH TAILLAMP CLIPS - SET <i>Ken</i>	1	30.00	30.00
REAR LH TAILLAMP LOWER GARNISH CLIPS - SET <i>Ken</i>	1	25.00	25.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

SG LEASING PTE LTD
15 YISHUN INDUSTRIAL ST 1 #01-08 WIN 5
SINGAPORE 768091

Contact : 94888856 98628321

TAX INVOICE

Repair Code : CLM16364

Date in : 18/07/2024

Vehicle Num. : GBF3605E

Model : TOYOTA HIACE DX 3.0 MANUAL

Chassis/Eng# : KDH2010194258/1KD2605553

Subtotal before discount	615.00
Percentage discount 0%	0.00
Sub-total 2	615.00
Parts-total	5,551.80

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall fender glass
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,530.00
Parts & Labour Total	8,081.80

*** This is a computer-generated document which requires no signature.***

page 2

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian Lj
4/s 19/07/24
050yjs

total: 4323.65

4/s 3-HK ✓