8/20/24, 11:10 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070316/RNP3M4

Date: 20/08/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002288157

Claimant Vehicle XE303R Insured Vehicle No : SFL207L

Date of Loss: 16/07/2024 Nature of Claim: TP Claim No: 367074

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: XE303R

Make & Model: IVECO STRALIS, 10.3 D AT440S46T/P EURO

V 60T (A) Engine No: F3AE3681YU022182913

Reg. Date: 30/01/2015 (Man. Year: 2013) Chassis No: WJMM1VTH4DC264298

Colour: Red Odometer: 299713 km

Engine Capacity: 10308 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

 Front Tyre Size:
 315/80R22.5
 Rear Tyre Size:
 315/80R22.5 (D)

 Front Left Side:
 366 8 mm
 Rear Left Side:
 366 8/8 mm

 Front Right Side:
 366 8 mm
 Rear Right Side:
 366 8/8 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
15,695.00	5,333.81	10,361.19	66.02
0.00	0.00	0.00	
1,770.00	1,200.00	570.00	32.20
0.00	0.00	0.00	
0.00	0.00	0.00	
(S\$) 17,465.00	6,533.81	10,931.19	62.59
(S\$)	5,200.00		
(\$\$) 17,465.00	5,200.00	12,265.00	70.23
(S\$) 1,571.85	468.00	1,103.85	70.23
(S\$) 19,036.85	5,668.00	13,368.85	70.23
	15,695.00 0.00 1,770.00 0.00 0.00 (\$\$) 17,465.00 (\$\$) (\$\$) 17,465.00 (\$\$)	15,695.00 5,333.81 0.00 0.00 1,770.00 1,200.00 0.00 0.00 0.00 0.00 (S\$) 17,465.00 6,533.81 (S\$) 5,200.00 (S\$) 17,465.00 5,200.00 (S\$) 1,571.85 468.00	15,695.00 5,333.81 10,361.19 0.00 0.00 0.00 1,770.00 1,200.00 570.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 (S\$) 17,465.00 6,533.81 10,931.19 (S\$) 5,200.00 (S\$) 17,465.00 5,200.00 12,265.00 (S\$) 1,571.85 468.00 1,103.85

INSPECTION

Date of Assignment: 19/07/2024

Date Inspected: 23/07/2024 Inspected At: R&S AUTOCLAIM PTE LTD (HQ)
13 PIONEER SECTOR 1, SINGAPORE 628424

13 FIONEER SECTOR 1, SINGAPORE 020424

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 05 Aug 2024)

Parts: N/A IVECO STRALIS 10.3 D AT440S46T/P EURO V 60T (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for XE303R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

	*FRONT BUMPER *FRONT BUMPER LOWER LH *FRONT BUMPER SIGNAL LAMP LH *HEAD LAMP LH *CORNER LAMP LH *FOG LAMP LH *STEP CENTRE LH	Scratched Cracked Not Necessary Not Necessary Not Necessary Not Necessary	10,720.00 F 250.00 F 235.00 F 1,485.00 F 390.00 F 260.00 F	*- FL *- FL *- FL
	*FRONT BUMPER SIGNAL LAMP LH *HEAD LAMP LH *CORNER LAMP LH *FOG LAMP LH	Not Necessary Not Necessary Not Necessary Not Necessary	235.00 F 1,485.00 F 390.00 F	*250.00 FL *- FL *- FL *- FL *- FL
	*HEAD LAMP LH *CORNER LAMP LH *FOG LAMP LH	Not Necessary Not Necessary Not Necessary	1,485.00 F 390.00 F	*- FL *- FL
	*CORNER LAMP LH *FOG LAMP LH	Not Necessary Not Necessary	390.00 F	*- FL
	*FOG LAMP LH	Not Necessary		
	· · · · · · · · · · · · · · · · · · ·	,	260.00 F	*- FL
	*STED CENTDE I H			
	SILF CLAIRL LII	Scratched	95.00 F	*95.00 FL
	*STEP LOWER LH	Missing	95.00 F	*95.00 FL
	*STEP COVER LH	Cracked	1,865.00 F	*1,520.00 FL
	*STEP SIDE SUPPORT BRACKET	Cut	300.00 F	*300.00 FL
e part. L=ListIte	nDisc.	_		
		Sub Total (S\$)	15,695.00	5,926.46
- List Item Discount on L Items 0.00/10.00% (S\$)				592.65
		Total Parts (S\$)	15,695.00	5,333.81
•	part. L=ListIter	*STEP SIDE SUPPORT BRACKET part. L=ListItemDisc.	*STEP SIDE SUPPORT BRACKET part. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 0.00/10.00% (S\$)	*STEP SIDE SUPPORT BRACKET Cut 300.00 F part. L=ListItemDisc. Sub Total (\$\$) 15,695.00 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT LH AREA	New	900.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISHING ON ACCIDENT LH AREA	New	750.00	600.00
3	TO CHECK AND RECTIFY WIRING CONNECT AND DISCONNET	New	120.00	0.00
	Gross Labour Cost (S\$)		1,770.00	1,200.00
	Report was unsubmitted during this	print-out.		-

< END OF ESTIMATES >