

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24070317/AVP3E2**Date:** 29/08/2024REFERENCE

Insured/Claimant:	NG KIM ENG	Policy No:	1800108415	
Date of Loss:	18/07/2024	Nature of Claim:	OD	Claim No: 6937334570SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1079L		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE697799
Reg. Date:	18/09/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V4J1080560
Colour:	Red	Odometer:	82523 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$78,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,800.00	2,662.32	8,137.68	75.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,752.00	2,172.00	3,580.00	62.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	16,552.00	4,834.32	11,717.68	70.79
+ GST 9.00/9.00% (\$\$)	1,489.68	435.09	1,054.59	70.79
Nett Amount (\$\$)	18,041.68	5,269.41	12,772.27	70.79

INSPECTION

Date of Assignment:	25/07/2024		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	23/07/2024	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,615.00 FS	*2,092.00 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	30.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	216.00 FS	*- FS
4	2		*REAR BUMPER ADAPTOR - LH / RH	Not Necessary	96.00 FS	*- FS
5	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	42.00 FS	*- FS
6	2		*REAR BUMPER GUIDE SECTION PIN - LH / RH	Not Necessary	75.00 FS	*- FS
7	1		*REAR BUMPER SPOILER	Deformed	297.00 FS	*237.20 FS
8	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	98.00 FS	*- FS
9	2		*REAR PARKING AID SENSOR	Not Necessary	572.00 FS	*- FS
10	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	11.00 FS	*- FS
11	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	736.00 FS	*- FS
12	2		*REAR BUMPER BRACKET - LH / RH	Not Necessary	74.00 FS	*- FS
13	1		*REAR LID	Repair	4,085.00 FS	*- FS
14	1		*REAR LID ATTACHMENT PARTS	Not Necessary	329.00 FS	*- FS
15	1		*REAR LID PACKING ADHESIVE	Necessary	23.00 FS	*18.32 FS
16	1		*REAR LID LOCK COVER	Not Necessary	9.00 FS	*- FS
17	1		*REAR LID LOCK	Not Necessary	227.00 FS	*- FS
18	1		*REAR LID WEATHER STRIP	Not Necessary	255.00 FS	*- FS
19	1		*AUDI EMBLEM	Necessary	162.00 FS	*129.20 FS
20	1		*A3 EMBLEM	Necessary	116.00 FS	*92.80 FS
21	1		*TFSI EMBLEM	Necessary	116.00 FS	*92.80 FS
22	1		*ULTRA EMBLEM	Not Necessary	116.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	10,800.00
						2,662.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT	New	280.00	0.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	500.00
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING	New	2,450.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (S\$)			5,752.00	2,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >