

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070318/UUA3Q2**Date:** 17/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MPC0002897_02
Claimant Vehicle No : GV1607U **Insured Vehicle No :** SMR6641L
Date of Loss: 18/07/2024 Nature of Claim: TP Claim No: MPC2024D0009581

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GV1607U**
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR (M) Engine No: 1KD2566564
Reg. Date: 15/12/2015 (Man. Year: 2015) Chassis No: JTFHT02P100182156
Colour: White Odometer: 152905 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Agilis 6 mm Rear Left Side: Agilis 6 mm
Front Right Side: Agilis 6 mm Rear Right Side: Agilis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,984.45	3,526.70	6,457.75	64.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	1,480.00	2,330.00	61.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,794.45	5,006.70	8,787.75	63.70
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	13,794.45	4,000.00	9,794.45	71.00
+ GST 9.00/9.00% (S\$)	1,241.50	360.00	881.50	71.00
Nett Amount (S\$)	15,035.95	4,360.00	10,675.95	71.00
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,760.00		

INSPECTION

Date of Assignment: 16/08/2024
Date Inspected: 16/08/2024 Inspected At: SPEEDWERKZ PTE LTD (Autobay) (HQ)
1 KAKI BUKIT AVENUE 6 #01-73
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Sep 2024)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GV1607U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	2,450.00 FL	*2,259.10 FL
2	1		*TAILGATE OUTER GARNISH	Not Necessary	182.40 FL	*- FL
3	1		*TAILGATE LOGO	Necessary	85.20 FL	*85.20 FL
4	1		*TAILGATE TOYOTA HIACE STICKER	Not Necessary	62.30 FL	*- FL
5	1		*TAILGATE INNER LOCK	Damaged	354.60 FL	*354.60 FL
6	1		*TAILGATE STRIKER	Not Necessary	126.30 FL	*- FL
7	1		*TAILGATE INNER TRIMBOARD	Not Necessary	286.70 FL	*- FL
8	1		*TAILGATE WEATHERSTRIP	Not Necessary	525.10 FL	*- FL
9	2		*TAILGATE DAMPER STAY L/R X2	Not Necessary	775.60 FL	*- FL
10	2		*TAILGATE NUMBER PLATE LAMP L/R X2	Not Necessary	146.40 FL	*- FL
11	1		*SET TAILGATE WINDSCREEN MOULDING	No such part	166.10 FL	*- FL
12	1		*TAIL LAMP L/R X2	N/S Cracked	986.60 FL	*386.20 FL
13	2		*TAIL LAMP LOWER OUTER GARNISH L/R	Repair	262.40 FL	*- FL
14	1		*REAR BUMPER	Dented	643.30 FL	*643.30 FL
15	2		*REAR BUMPER SIDE RETAINER L/R	Not Necessary	98.80 FL	*- FL
16	2		*REAR BUMPER LOWER BRACKET L/R	Bent	82.60 FL	*82.60 FL
17	1		*END PANEL OUTER PANEL	Dented / Bent	464.60 FL	*464.60 FL
18	1		*END PANEL INNER PANEL	Repair	1,420.00 FL	*- FL
19	2		*END PANEL SIDE EXTENSION PANEL L/R	Repair	786.20 FL	*- FL
20	1		*END PANEL GARNISH	Not Necessary	135.60 FL	*- FL
21	1		*SPARE TYRE BRACKET	Not Necessary	380.10 FL	*- FL
22	1		*SET SPARE TYRE LOCK	Not Necessary	286.40 FL	*- FL
23	1		*REAR EXHAUST MUFFLER	Not Necessary	845.30 FL	*- FL
24	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
25	1		*SET REVERSE CAMERA	Serviceable	380.00 FS	*- FS
26	1		*SET REVERSE SENSOR	Cracked	300.00 FS	*200.00 FS
27	1		*TAILGATE TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
28	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS
30	1		*TAILGATE WINDSCREEN SPONGE	Not Necessary	80.00 FS	*- FS
31	1		*TAILGATE 70KM/H STICKER	Necessary	50.00 FS	*10.00 FS
32	1		*END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*END PANEL SEALANT	Necessary	100.00 FS	*40.00 FS
34	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,872.60	4,595.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,888.15	1,068.90
Total Parts (\$\$)	9,984.45	3,526.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING	New	50.00	20.00
2	TO REPLACE REAR REVERSE SENSOR	New	80.00	30.00
3	TO REPLACE REAR REVERSE CAMERA	New	100.00	0.00
4	TO REPLACE REAR WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REPLACE TAILGATE FITTINGS	New	120.00	50.00
6	TO REMOVE AND REPLACE REAR INTERIOR TRIMS & GARNISH	New	200.00	0.00
7	TO PROVIDE LABOUR WORKMANSHIP	New	1,400.00	600.00
8	TO SPRAY PAINT ON AFFECTED PANELS	New	1,400.00	600.00
9	TO REMOVE AND REPLACE REAR EXHAUST MUFFLER	New	160.00	0.00
10	RUST PROOFING	New	150.00	60.00
Gross Labour Cost (\$\$)			3,810.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >