

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070319/UMA3Q2
Date: 11/10/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176362		
Claimant Vehicle No :	SLT1331R	Insured Vehicle No :	SMX239Z		
Date of Loss:	20/07/2024	Nature of Claim:	TP	Claim No:	4134035470SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1331R	Engine No:	2ZR2Z14614
Make & Model:	TOYOTA NOAH HYBRID, 1.8 (A)	Chassis No:	ZWR900162056
Reg. Date:	31/05/2024 (Man. Year: 2024)	Odometer:	5183 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,833.75	4,255.65	4,578.10	51.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	2,020.00	1,900.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,753.75	6,275.65	6,478.10	50.79
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	12,753.75	5,000.00	7,753.75	60.80
+ Car Rental (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		5,873.18		
Global Sum Settlement (S\$)		5,850.00		

INSPECTION

Date of Assignment:	22/07/2024		
Date Inspected:	22/07/2024	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR WINDSCREEN MOULDING	Necessary	180.30 FL	*108.00 FL	
2	1		*REAR TAILGATE	Dented / Bent	1,812.30 FL	*1,812.30 FL	
3	1		*REAR TAILGATE RUBBER	Twisted	388.75 FL	*388.75 FL	
4	1		*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	100.07 FL	*100.07 FL	
5	1		*REAR TAILGATE LOGO	Not Necessary	130.20 FL	*- FL	
6	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	488.96 FL	*- FL	
7	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	187.30 FL	*- FL	
8	1		*REAR TAILGATE INNER LOCK	Damaged	244.30 FL	*244.30 FL	
9	2		*REAR TAILGATE DAMPERS	Not Necessary	733.00 FL	*- FL	
10	2		*REAR TAILLAMPS	Not Necessary	1,176.66 FL	*- FL	
11	2		*REAR TAILLAMPLOWER GARNISHES	Not Necessary	466.40 FL	*- FL	
12	1		*REAR END PANEL	Dented	1,003.33 FL	*900.20 FL	
13	1		*REAR END PANEL INNER GARNISH	Twisted	189.75 FL	*189.75 FL	
14	1		*REAR BUMPER	Deformed / Torn	1,203.75 FL	*1,203.75 FL	
15	2		*REAR BUMPER BRACKETS	Not Necessary	160.66 FL	*- FL	
16	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	181.94 FL	*- FL	
17	2		*REAR BUMPER REFLECTORS	Not Necessary	241.08 FL	*- FL	
18	1		*REAR REVERSE CAMERA	Not Necessary	488.96 FL	*- FL	
19	1		*REAR FLOOR BOARD	Cracked	233.75 FL	*233.75 FL	
20	1		*REAR FLOOR PANEL	Repair	1,300.21 FL	*- FL	
21	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS	
22	1		*SET REAR BUMPER CLIP	Necessary	90.00 FS	*30.00 FS	
23	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS	
24	1		*SET REAR REVERSE SENSOR	Cracked	350.00 FS	*220.00 FS	
25	1		*SET TAILGATE OUTER STEP PROTECTOR	Twisted	80.00 FS	*80.00 FS	
					Sub Total (\$\$)	11,561.67	5,550.87
					- List Item Discount on L Items 25.00/25.00% (\$\$)	2,727.92	1,295.22
					Total Parts (\$\$)	8,833.75	4,255.65

F=Franchise part. S=SpcNett. L=ListItemDisc.

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
3	TO REMOVE AND REPLACED REAR REVERSE SENSOR	New	150.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UINDERCOATING	New	150.00	50.00
7	PANEL BEATING	New	1,600.00	800.00
8	TO RESPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	880.00
Gross Labour Cost (\$\$)			3,920.00	2,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >