

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070320/UMA3Q2**Date:** 18/11/2024REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7240008807
Claimant Vehicle No : SLS6215R **Insured Vehicle No :** SNQ686R
 Date of Loss: 19/07/2024 Nature of Claim: TP Claim No: 9122641018SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS6215R**
 Make & Model: VOLKSWAGEN POLO GP, 1.2 TSI 6C13EZ SR Engine No: CJZD34593
 LED (A)
 Reg. Date: 28/09/2017 (Man. Year: 2017) Chassis No: WVVZZZ6RZHU056182
 Colour: Black Odometer: 117202 km
 Engine Capacity: 1197 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	952.85	93.10	859.75	90.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,320.00	520.00	800.00	60.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,272.85	613.10	1,659.75	73.03
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		29.43		
Nett Liability (S\$)		842.53		

INSPECTION

Date of Assignment: 23/07/2024
 Date Inspected: 23/07/2024 Inspected At: Hup Motor Trading & Service (HQ)
 Blk 9004 Tampines Street 93, #01-120
 Singapore 528838
 Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Recommended Parts

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	50.00	20.00
2	TO REMOVE & REFIX CARPET ,FLOOR BOARD COVER ,FLOOR MAT GARNISH ,TOOL SET ,SPARE TYRE & NECESSARY PARTS	New	120.00	0.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR N/S FENDER & NECESSARY PARTS,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	500.00	200.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	650.00	300.00
Gross Labour Cost (\$\$)			1,320.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >