

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070324/AUA3Q2**Date:** 14/01/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070172332
Claimant Vehicle No : SMY3888A **Insured Vehicle No :** SMX36S
 Date of Loss: 12/07/2024 Nature of Claim: TP Claim No: 4442882564SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY3888A**
 Make & Model: BMW X1 SDRIVE18I, 1.5 LED NAV (A) Engine No: 38465477B38A15A
 Reg. Date: 28/11/2018 (Man. Year: 2018) Chassis No: WBAJG12070EN49147
 Colour: Black Odometer: 84571 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,380.25	4,141.28	7,238.97	63.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,930.00	1,800.00	4,130.00	69.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,310.25	5,941.28	11,368.97	65.68
Approved Total (Overridden) (S\$)		4,750.00		
(S\$)	17,310.25	4,750.00	12,560.25	72.56
+ GST 9.00/9.00% (S\$)	1,557.92	427.50	1,130.42	72.56
Nett Amount (S\$)	18,868.17	5,177.50	13,690.67	72.56
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
Nett Liability (S\$)		5,597.50		

INSPECTION

Date of Assignment: 15/07/2024
 Date Inspected: 15/07/2024 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (UPPER)	Deformed	723.45 FL	*723.45 FL
2	1		*REAR BUMPER (LOWER)	Deformed	454.80 FL	*454.80 FL
3	1		*REAR BUMPER DIFFUSER	Deformed	370.90 FL	*370.90 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	118.30 FL	*- FL
5	1		*REAR BUMPER SENSOR (4 PCS)	Damaged (1 PCS ONLY)	994.80 FL	*248.70 FL
6	1		*REAR BUMPER SENSOR HOLDER (4 PCS)	Necessary (1 PCS ONLY)	277.40 FL	*69.35 FL
7	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	588.45 FL	*- FL
8	1		*REAR BUMPER TOWING COVER	Not Necessary	35.35 FL	*- FL
9	1		*REAR BUMPER REINFORCEMENT	Dented	579.90 FL	*579.90 FL
10	2		*REAR BUMPER SMART OPEN SENSOR GARNISH BRACKET	Not Necessary	90.60 FL	*- FL
11	1		*REAR BUMPER SMART OPEN SENSOR GARNISH	Not Necessary	164.35 FL	*- FL
12	2		*REAR BUMPER SIDE BRACKET (PLATIC)	Not Necessary	295.90 FL	*- FL
13	2		*REAR BUMPER CENTER BRACKET (UPPER)	Cracked	347.70 FL	*347.70 FL
14	2		*REAR WHEEL ARCED GARNISH	Not Necessary	595.70 FL	*- FL
15	1		*TAIL LAMP	N/S Cracked	728.20 FL	*364.10 FL
16	1		*TAILGATE DETECTOR	Not Necessary	798.45 FL	*- FL
17	1		*TAILGATE SMART OPEN SENSOR	Not Necessary	333.90 FL	*- FL
18	1		*TAILGATE SMART OPEN SENSOR BRACKET	Cracked	148.60 FL	*148.60 FL
19	1		*REAR END PANEL	Dented	747.40 FL	*747.40 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	146.45 FL	*146.45 FL
21	1		*TOOLS COMPARTMENT	Not Necessary	194.60 FL	*- FL
22	1		*REAR EXHAUST PIPE WITH MUFFLER	Not Necessary	1,465.05 FL	*- FL
23	4		*REAR EXHAUST MOUNTING	Not Necessary	139.40 FL	*- FL
24	1		*REAR EXHAUST PIPE BRACKET	Not Necessary	96.45 FL	*- FL
25	1		*REAR EXHAUST MUFFLER INSULATOR (REAR)	Not Necessary	193.75 FL	*- FL
26	1		*REAR EXHAUST MUFFLER INSULATOR (CENTER)	Not Necessary	329.45 FL	*- FL
27	2		*REAR EXHAUST CHROME PIPE	Not Necessary	335.70 FL	*- FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER (UPPER) CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*SET REAR BUMPER (LOWER) CLIP	Necessary	80.00 FS	*20.00 FS
31	1		*SET REAR BUMPER DIFFUSER CLIP	Necessary	60.00 FS	*20.00 FS
32	1		*SET TAILLAMP CLIP	Not Necessary	60.00 FS	*- FS
33	1		*SET REAR FENDER ARCED GARNISH RIVERT	Not Necessary	60.00 FS	*- FS
34	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
35	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
36	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 11,945.00 4,351.35
- List Item Discount on L Items 5.00/5.00% (S\$) 564.75 210.07

Total Parts (S\$) 11,380.25 4,141.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	600.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	250.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	150.00	50.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	100.00	50.00
8	REMOVE AND REFIX VIDEO RECORDER	New	100.00	0.00
9	RESET SMART OPENER	New	350.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	680.00	150.00
Gross Labour Cost (\$\$)			5,930.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >