

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO24070329/Anc 50 RAFFLES PLACE #03-03 Date: 21/08/2024 SINGAPORE LAND TOWER SINGAPORE 048623 Code: SMO 1. Policy Particulars :- PRE-REPAIR SURVEY Insured Veh. SMF 9505R Veh. Inspected GBJ 492L Policy No. D24MTPV01006905 n Coverage Claim No. CMTD2402349/SYH **Excess** \$0.00 **GRACE TEO** 22/07/2024 Assign From **Assign Date** 2. **Vehicle Details** TOYOTA HIACE C.C 2982 Make & Model 1KD2829088 04/12/2018 Engine No. Year of Reg. JTFHT02P500245758 Colour **BLUE** Chassis No. IN ORDER Odometer 122621 KM Steering **Brakes** IN ORDER General GOOD RIMS: NIL Modification(s) 3. Conditions of Tyres Size Make Balance (mm) 195R15C **MICHELIN** 6 R/H Front Tyre 195R15C L/H Front Tyre **MICHELIN** 6 6 195R15C **MICHELIN** R/H Rear Tyre 195R15C **MICHELIN** 6 L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. 5. **General Information** 17/07/2024 **Inspection Date Accident Date** 22/07/2024 (15:01) Survey held at HOCK MOTORS WORKSHOP NO.1 KAKI BUKIT AVE 6 #02-38 AUTOBAY @KAKI BUKIT SINGAPORE 417883 Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

LWP

5b.

ADRIAN LING WAI PING

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500-\$3,500

Estimate Days of Repair