



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SND 960S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TORN	\$520.80	\$520.80
1	REAR BUMPER LOWER (BLACK)	NOT NECESSARY	\$380.60	\$0.00
2	REAR BUMPER SIDE RETAINER @\$48.90	N/S CRACKED	\$97.80	\$48.90
4	REAR BUMPER BRACKET @\$48.00	NOT NECESSARY	\$192.00	\$0.00
2	REAR BUMPER REFLECTOR @\$48.00	NOT NECESSARY	\$96.00	\$0.00
4	REAR BUMPER REVERSE SENSOR HOLDER @\$48.00	NOT NECESSARY	\$192.00	\$0.00
1	REAR BUMPER MUDFLAP LH	NOT NECESSARY	\$142.30	\$0.00
1	REAR BUMPER SIDE INNER LOWER GARNISH RH	NOT NECESSARY	\$98.60	\$0.00
1	TAILLAMP LH	NOT NECESSARY	\$956.00	\$0.00
1	REAR FENDER AIR VENT LH	CRACKED	\$88.60	\$88.60
1	REAR FENDER INNER COWLING LH	NOT NECESSARY	\$189.20	\$0.00
1	REAR ABS SENSOR LH	NOT NECESSARY	\$394.50	\$0.00
1	REAR WHEEL HUP C/W BEARING LH	NOT NECESSARY	\$452.30	\$0.00
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	\$230.50	\$0.00
1	REAR AXLE	NOT NECESSARY	\$1,248.10	\$0.00
1	REAR BLIND SPOT LH	NOT NECESSARY	\$1,296.40	\$0.00
1	REAR BLIND SPOT BRACKET LH	NOT NECESSARY	\$169.30	\$0.00
	LESS 20.00% DISCOUNT		(\$1,349.00)	(\$131.66)
			\$5,396.00	\$526.64

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	SET TAIL LAMP CLIP (SN)	NOT NECESSARY	\$40.00	\$0.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	\$80.00	\$0.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR WHEEL TYRE RH (SN)	NOT NECESSARY	\$400.00	\$0.00
1	REAR WHEEL RIM RH (SN)	NOT NECESSARY	\$850.00	\$0.00
1	BRAKE OIL (SN)	NOT NECESSARY	\$30.00	\$0.00
			\$1,560.00	\$30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,200.00	\$200.00
	TO SPRAY PAINT AFFECTED AREA		\$1,200.00	\$200.00
	TUFF COAT	NOT NECESSARY	\$250.00	\$0.00
	WIRING CHECK		\$180.00	\$30.00
	REMOVE AND REFIX UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	NOT NECESSARY	\$350.00	\$0.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$80.00	\$50.00
	CONDUCT WATER LEAKAGE TEST	NOT NECESSARY	\$80.00	\$0.00
	REMOVE AND REFIX REAR UNDER CARRIAGE	NOT NECESSARY	\$650.00	\$0.00
	RESET ABS LIGHT	NOT NECESSARY	\$350.00	\$0.00
	FOUR WHEEL ALIGNMENT	NOT NECESSARY	\$120.00	\$0.00
	REMOVE AND REFIX REAR BLIND SPOT SENSOR AND RECODING AND CALIBRATION	NOT NECESSARY	\$800.00	\$0.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC	NOT NECESSARY	\$250.00	\$0.00
			\$5,510.00	\$480.00
GRAND TOTAL			\$12,466.00	\$1,036.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$800.00
Report Ref No: CS/FCI24070330/Avh3m4				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.