



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070330/Avh3m4
16 RAFFLES QUAY	Date:	23/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3032C	Veh. Inspected	SND 960S
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005961MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	22/07/2024

2. Vehicle Details

Make & Model	HYUNDAI CN7 AVANTE	C.C	1598
Engine No.	G4FMMU082928	Year of Reg.	22/10/2021
Chassis No.	KMHLN41ETNU241350	Colour	GREY
Odometer	30956 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	HANKOOK	6
L/H Front Tyre	205/55R16	HANKOOK	6
R/H Rear Tyre	205/55R16	HANKOOK	6
L/H Rear Tyre	205/55R16	HANKOOK	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspection Date	23/07/2024
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days