



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 688C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	2,510.00	2,310.00
1	FRONT BUMPER SIDE HOLDER	NOT NECESSARY	165.00	-
1	FRONT BUMPER SENSOR	NOT NECESSARY	290.00	-
1	FRONT FENDER	DENTED	1,285.00	1,285.00
1	FRONT FENDER INNER SHIELD	NOT NECESSARY	293.00	-
1	HEADLAMP	NOT NECESSARY	3,989.00	-
1	FRONT DOOR	TO REPAIR SEE LABOUR	2,959.00	-
1	FRONT DOOR WEATHERSTRIPE	NOT NECESSARY	269.00	-
2	FRONT DOOR OUTER HANDLE	NOT NECESSARY	221.00	-
1	FRONT DOOR WING MIRROR	NOT NECESSARY	1,405.00	-
1	FRONT DOOR WING MIRROR COVER	CUT	121.00	121.00
1	FRONT DOOR WING MIRROR SIGNAL LAMP	CUT	141.00	141.00
1	FRONT DOOR WING MIRROR GLASS	NOT NECESSARY	689.00	-
1	REAR DOOR	DENTED	2,893.00	2,893.00
1	REAR DOOR WEATHERSTRIPE	NECESSARY	287.00	287.00
1	REAR DOOR OUTER HANDLE	DAMAGED	240.00	240.00
1	REAR BUMPER	DEFORMED	2,799.00	2,599.00
1	REAR BUMPER SIDE HOLDER	NOT NECESSARY	157.00	-
1	REAR BUMPER SENSOR	NOT NECESSARY	295.00	-
1	REAR BUMPER REFLECTOR	NOT NECESSARY	98.00	-
1	TAILLAMP	CRACKED	1,188.00	905.00
	LESS 10% DISCOUNT		-2,229.40	-1,078.10
			20,064.60	9,702.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRONT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	30.00	-
1	FRONT WHEEL RIM (SN)	NOT NECESSARY	1,500.00	-
1	FRONT TYRE (SN)	NOT NECESSARY	350.00	-

Report Ref No. CS/AWA24070335/Avce2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			1,980.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR.		1,400.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,400.00	1,000.00
	WIRING CHECK.		100.00	30.00
	TO APPLY TUFF COAT.		150.00	30.00
	TO REMOVE FRONT BUMPER SENSOR.		100.00	50.00
	TO TRANSFER FRONT & REAR DOOR FITTINGS.		300.00	60.00
	TO REMOVE REAR BUMPER SENSOR.		100.00	50.00
	TO PERFORM WHEEL ALIGNMENT.	NOT NECESSARY	150.00	-
	TO PERFORM DIAGNOSTIC TEST.	NOT NECESSARY	250.00	-
		3,950.00	2,020.00	
GRAND TOTAL			25,994.60	11,822.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,400.00

Report Ref No. CS/AWA24070335/Avce2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.