

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070336/RPA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MVC0008311
Claimant Vehicle No : SMR5310Z **Insured Vehicle No :** YR317X
 Date of Loss: 17/07/2024 Nature of Claim: TP Claim No: MCV2024D0008320

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR5310Z**
 Make & Model: MERCEDES-BENZ A200, 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A) Engine No: 28291480270087
 Reg. Date: 13/01/2020 (Man. Year: 2019) Chassis No: WDD1771872J157208
 Colour: White Odometer: 49263 km
 Engine Capacity: 1332 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,685.07	2,646.67	4,038.40	60.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	4,980.00	200.00	3.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,865.07	7,626.67	4,238.40	35.72
+ GST 9.00/9.00% (S\$)	1,067.86	686.40	381.46	35.72
Nett Amount (S\$)	12,932.93	8,313.07	4,619.86	35.72
+ Car Rental (6.0 x S\$100.00/day + 9.00% GST) (S\$)		654.00		
Nett Liability (S\$)		8,967.07		

INSPECTION

Date of Assignment: 21/08/2024
 Date Inspected: 21/08/2024 Inspected At: Cycle & Carriage Industries Pte Ltd (Pandan Loop)
 188 Pandan Loop
 Singapore 128378
 Estimated Period of Repair: 4.0 days

Adjuster: CHEW HSIAO TONG**Manager:** MOHD RASUL

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2024)
Parts:	144	MERCEDES-BENZ A200 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR5310Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	15.00 FS	*15.00 FS
2	1		*TRUNK LID	Repair	2,981.87 FS	*- FS
3	1		*MERCEDES STAR	Necessary	66.44 FS	*66.44 FS
4	3		*GROMMET	Necessary	9.33 FS	*9.33 FS
5	1		*A200 MODEL PLATE	Necessary	153.42 FS	*153.42 FS
6	1		*REAR BUMPER	Deformed	1,520.51 FS	*1,520.51 FS
7	1		*REAR BUMPER LOWER TRIM	Cut	555.27 FS	*555.27 FS
8	1		*CTR/REAR BUMPER LOWER CHROME	Cut	326.70 FS	*326.70 FS
9	1		*REAR SWITCH MODULE	Not Necessary	184.33 FS	*- FS
10	1		*COUPLING HOUSING	Not Necessary	15.64 FS	*- FS
11	1		*REAR BUMPER HOLDER	Not Necessary	100.62 FS	*- FS
12	1		*CTR /BASIC CARRIER FOR BUMPER	Not Necessary	192.13 FS	*- FS
13	1		*REAR CROSS MEMBER	Not Necessary	563.81 FS	*- FS
F=Franchise part. S=SpcNett.						
					Total Parts (S\$)	6,685.07 2,646.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	2,880.00	2,880.00
2	RESPRAY BOOT LID & REAR BUMPER	New	1,800.00	1,600.00
3	USING XENTRY DIAGNOTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STADARD	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (\$\$)			5,180.00	4,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >