3/18/25, 3:14 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24070337/APA3Q2

Date: 18/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MCV0005692_04

Claimant Vehicle GV6444P Insured Vehicle No: GBH9486G

No:

Date of Loss: 19/07/2024 Nature of Claim: TP Claim No: MCV2024D0008531

DESCRIPTION & IDENTIFICATION OF VEHICLE

GV6444P Reg No:

Make & Model: TOYOTA HIACE, 2.0 DX (A) Engine No: 1TR2372357 TRH2000345700 Reg. Date: 29/08/2022 (Man. Year: 2021) Chassis No: Odometer: 45514 km

Colour: White 1998 cc **Engine Capacity:**

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

COOT OF OLABO

195R15 195R15 Front Tyre Size: Rear Tyre Size:

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,671.45	1,693.15	6,978.30	80.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,190.00	760.00	3,430.00	81.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total	al (S\$) 12,861.45	2,453.15	10,408.30	80.93
Approved Total (Overridder	n) (S\$)	1,900.00		
Nett Amour	nt (S\$) 12,861.45	1,900.00	10,961.45	85.23
+ Loss of Us	+ Loss of Use (4.0 x S\$80.00/day) (S\$)			
+ Doc/Search Fee (S\$)		27.25		
	Nett Liability (S\$)	2,247.25		

INSPECTION

24/07/2024 Date of Assignment:

Kt Motorwerk (HQ) Date Inspected: 24/07/2024 Inspected At:

Blk 3012 Bedok Industrial Park E, #01-2020

Singapore 489978

Estimated Period of Repair: 4.0 days

Adjuster: **ADRIAN LING CHEW HSIAO TONG** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Feb 2025)

Parts: 213 TOYOTA HIACE 2.0 DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GV6444P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Not Necessary	605.80 FL	*- FL
2	1	*REAR BUMPER SIDE RETAINERS	Not Necessary	185.20 FL	*- FL
3	1	*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL
4	1	*TYRE CASE	Cut	350.00 FL	*100.00 FS
5	1	*REAR FLOOR PANEL (REAR PORTION)	Not Necessary	1,148.50 FL	*- FL
6	1	*REAR FENDER LH	Dented	1,958.60 FL	*1,958.60 FL
7	1	*REAR INNER FENDER LH	Repair	1,685.20 FL	*- FL
8	1	*REAR FENDER MUDFLAP LH	Cut	85.60 FL	*85.60 FL
9	1	*REAR FENDER AIR DUCT	Not Necessary	105.70 FL	*- FL
10	1	*REAR FENDER INNER COVER	Not Necessary	98.70 FL	*- FL
11	1	*REAR FENDER INNER TRIM	Not Necessary	356.80 FL	*- FL
12	1	*REAR FENDER SIDE DOOR RAILING	Not Necessary	648.70 FL	*- FL
13	1	*REAR ABSORBER	Not Necessary	325.90 FL	*- FL
14	1	*REAR WHEEL HUB BEARING	Not Necessary	298.20 FL	*- FL
15	1	*REAR LEAF SPRING BRACKET	Not Necessary	371.20 FL	*- FL
16	1	*REAR LEAF SPRING LH	Not Necessary	1,394.50 FL	*- FL
17	1	*BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*60.00 FS
18	1	*FLOOR PANEL VINYL MAT	Not Necessary	450.00 FS	*- FS
19	1	*TYRE	Not Necessary	250.00 FS	*- FS
20	1	*REAR FLOOE PANEL WOODEN BOARD	Not Necessary	600.00 FS	*- FS
F=Fra	anchise part. S=Spcl	Nett. L=ListItemDisc.	_		
			Sub Total (S\$)	11,088.60	2,204.20
		- List Item Discount on	L Items 25.00/25.00% (S\$)	2,417.15	511.05
			Total Parts (S\$)	8,671.45	1,693.15

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			,
1	PANEL BEATING.	New	1,400.00	400.00
2	SPRAY PAINTING.	New	1,400.00	250.00
3	ANTI RUST.	New	20.00	0.00
4	REMOVE AND INSTALL WOODEN BOARD.	New	200.00	0.00
5	4 WHEEL ALIGHTMENT.	New	120.00	80.00
6	REMOVE REAR UNDERCARRIAGE.	New	300.00	0.00
7	REPAIR AND REALIGH CHASSIS MEMBER.	New	350.00	0.00
8	TO APPLY UNDERCOAT AND SEALANT TO AFFECTED AREA.	New	280.00	0.00
9	CHECK WIRING ON TAILAMPS.	New	120.00	30.00
	Gross Labour Cost (S\$)		4,190.00	760.00
	Report was unsubmitted during t	nis print-out.		

< END OF ESTIMATES >