

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24070339/KNH3M4
Date: 23/08/2024

REFERENCE				
Insured/Claimant:	TSG FOOD PTE LTD	Policy No:	MCF24B00000200	
Date of Loss:	19/07/2024	Nature of Claim:	OD	Claim No: DMCF2400032H/ST

<u>DESCRIPTION & IDENTIFICATION OF VEHICLE</u>			
Reg No:	YP1243D		
Make & Model:	MITSUBISHI FEB21CR4SDEB, 3.0 D (M)	Engine No:	4P10B98069
Reg. Date:	02/02/2016 (Man. Year: 2015)	Chassis No:	FEB21CA20001
Colour:	Yellow	Odometer:	390971 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	S\$30,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY				
General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

<u>CONDITION OF TYRES</u>			
Front Tyre Size:	195R15X8	Rear Tyre Size:	195R15X8 (D)
Front Left Side:	Falken 8 mm	Rear Left Side:	Falken 8/8 mm
Front Right Side:	Falken 8 mm	Rear Right Side:	Falken 8/8 mm
<i>The above values represent the remaining tyre treads depth</i>			

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,476.50	6,457.00	3,019.50	31.86
Miscellaneous Items	280.00	224.00	56.00	20.00
Labour	2,400.00	2,010.00	390.00	16.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,156.50	8,691.00	3,465.50	28.51
Approved Total (Overridden) (S\$)		6,950.00		
- Excess (S\$)	0.00	600.00	-600.00	
(S\$)	12,156.50	6,350.00	5,806.50	47.76
+ GST 9.00/9.00% (S\$)	1,094.09	571.50	522.59	47.76
Nett Amount (S\$)	13,250.59	6,921.50	6,329.09	47.76

<u>INSPECTION</u>			
Date of Assignment:	22/07/2024	Present Location:	Cheng Hoe Motor Pte Ltd (Yishun) CHENG HOE MOTOR PTE LTD
Date Inspected:	23/07/2024	Inspected At:	BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761
Estimated Period of Repair:	7.0 days		

Adjuster: KENNETH KONG

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 23 Aug 2024)	
Parts:	N/A	MITSUBISHI FEB21CR4SDEB 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP1243D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 pc front LH side mirror stay (WCP)	Bent	190.00 F	*190.00 F
2	1		*1 pc front LH side mirror round (WCP)	Cracked	35.00 F	*35.00 F
3	1		*1 pc front LH side mirror square (WCP)	Cover Missing	60.00 F	*60.00 F
4	1		*1 pc front LH side mirror stay top garnish (WCP)	Missing	30.00 F	*30.00 F
5	1		*1 pc front LH side cornal panel (WCP)	Cracked	250.00 F	*250.00 F
6	1		*1 pc LH headlamp (WCP)	Mtg Cracked	260.00 F	*260.00 F
7	1		*1 pc LH signal lamp (WCP)	Broken	120.00 F	*120.00 F
8	1		*1 pc LH side reflector (WCP)	Missing	110.00 F	*110.00 F
9	1		*1 pc front bumper LH side pad (WCP)	Cut	160.00 F	*160.00 F
10	1		*1 pc front bumper RH side pad (WCP)	Missing	160.00 F	*160.00 F
11	1		*1 pc RH headlamp (WCP)	Split	240.00 F	*240.00 F
12	1		*1 pc RH signal lamp (WCP)	Missing	240.00 F	*240.00 F
13	1		*1 pc front bumper (WCP)	Buckled	380.00 F	*380.00 F
14	1		*1 pc front RH cornal panel (WCP)	Cracked	250.00 F	*250.00 F
15	1		*1 pc front RH side mirror (WCP)	Distorted	60.00 F	*60.00 F
16	1		*1 pc front LH door light (WCP)	Cracked	40.00 F	*40.00 F
17	1		*1 pc front RH tyre rim (WCP)	Dented	280.00 F	*280.00 F
18	1		*1 pc front RH top arm (WCP)	Distorted	1,800.00 F	*1,800.00 F
19	1		*1 pc front RH lower arm (WCP)	Serviceable	1,300.00 F	*- F
20	1		*1 pc front RH knuckle arm (WCP)	Serviceable	1,300.00 F	*- F
21	1		*1 pc front RH bearing (WCP)	Not Necessary	40.00 F	*- F
22	1		*1 pc radiator fan cowlng (WCP)	Cracked	220.00 F	*220.00 F
23	1		*1 pc radiator fan blade (WCP)	Serviceable	105.00 F	*- F
24	1		*1 pc power steering oil spare tank (WCP)	Cracked	520.00 F	*520.00 F
Supplementary #1						
25	1		*1 pc front LH door inner lock (WCP)	Dented	260.00 F	*260.00 F
26	1		*1 pc front bumper LH bracket (WCP)	Bent	110.00 F	*110.00 F
27	1		*1 pc room mirror (WCP)	Missing	95.00 F	*95.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Sub Total (S\$)					8,615.00	5,870.00
+ Margin on L,N Items 10.00/10.00% (S\$)					861.50	587.00
Total Parts (S\$)					9,476.50	6,457.00
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 pc front RH tyre (80%) (Torn)	280.00	224.00
Sub Total (\$\$)			280.00	224.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Towing (by owner) (NPA)	New	-	0.00
2	Remove & refix frt bumper assy,grille,headlamps,side mirrors;to straighten,knocking & repair front LH windscreen pillar,repair frt both doors,frt LH floorboard panel & realign cabin position	New	900.00	750.00
3	Remove & refix dashboard,meter assy & check wiring	New	250.00	180.00
4	Putty & respray on frt bumper,both cornal panel,frt LH windscreen pillar,frt both door	New	900.00	800.00
5	Remove & refix frt RH undercarriage,check steering & wheel alignment	New	350.00	280.00
Gross Labour Cost (\$\$)			2,400.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >