



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070341/Uvh3
75 BRAS BASAH ROAD	Date:	08/08/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNH 5671Y	Veh. Inspected	GBK 178P
Policy No.	-	Coverage	0
Claim No.	MT/1286936-003	Excess	\$0.00
Assign From	JULIE MANGUBAT	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	TOYOTA HIACE	C.C	2982
Engine No.	1KDB016816	Year of Reg.	27/11/2019
Chassis No.	JTFHT02P400249901	Colour	WHITE
Odometer	105403 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	YOKOHAMA	6
L/H Front Tyre	195R15	YOKOHAMA	6
R/H Rear Tyre	195R15	BRIDGESTONE	6
L/H Rear Tyre	195R15	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/07/2024	Inspection Date	23/07/2024 (09:14)
Survey held at	522 BEDOK NORTH AVE 1, #01-96 S 460522 - REPAIRER: YEW HOK AUTO SERVICES		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days