



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMM 3525K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR AXLE	NOT NECESSARY	\$3,516.80	\$0.00
1	REAR BUMPER	DEFORMED	\$810.20	\$810.20
1	REAR BUMPER RH REFLECTOR	CRACKED	\$81.80	\$81.80
2	REAR BUMPER SIDE RETAINER L/R @\$109.60	O/S CRACKED	\$219.20	\$109.60
1	REAR RH DOOR	TO REPAIR SEE LABOUR	\$2,711.40	\$0.00
1	REAR RH FENDER	DENTED	\$2,012.00	\$1,450.00
1	REAR RH FENDER INNER SHIELD	DEFORMED	\$371.70	\$245.00
1	REAR RH FENDER WINDOW GLASS WITH MOULDING	NOT NECESSARY	\$1,268.20	\$0.00
1	REAR RH SHOCK ABSORBER	NOT NECESSARY	\$162.50	\$0.00
1	REAR RH TAILLAMP LOWER GARNISH	DEFORMED	\$283.90	\$283.90
1	REAR RH TAILLAMP LOWER GARNISH SIDE BRACKET	CRACKED	\$240.40	\$240.40
1	REAR RH WHEEL BEARING	NOT NECESSARY	\$1,228.80	\$0.00
	<b>LESS 25.00% DISCOUNT</b>		(\$3,226.73)	(\$805.23)
			<b>\$9,680.17</b>	<b>\$2,415.67</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT RADIO (SN)	DAMAGED	\$2,000.00	\$180.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	\$80.00	\$30.00
1	REAR RH 215/50R17 TYRE (SN)	NOT NECESSARY	\$500.00	\$0.00
1	SET REAR RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	REAR RH FENDER WINDOW GLASS SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
1	REAR RH SPORT RIM (SN)	CUT	\$980.00	\$500.00
1	SET REAR RH TAILLAMP LOWER GARNISH CLIPS (SN)	NECESSARY	\$50.00	\$20.00
			<b>\$3,740.00</b>	<b>\$730.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR		\$80.00	\$80.00
	TO REMOVE, REINSTALL FENDER GLASS		\$120.00	\$60.00



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	NOT NECESSARY	\$380.00	\$0.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,300.00	\$700.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR RH DOOR		\$1,000.00	\$600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$100.00	\$30.00
			\$3,080.00	\$1,550.00
GRAND TOTAL			\$16,500.17	\$4,695.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,700.00
Report Ref No: CS/INC24070342/Aqh3m4				

TOTAL FOR SPARE PARTS: \$13,420.17 \$ 3,145.67  
TOTAL FOR LABOUR : \$ 3,080.00 \$ 1,550.00  
TOTAL REPAIR COST: \$16,500.17 \$ 4,695.67

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.