



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMT 403L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT O/S FENDER	DENTED	\$1,549.12	\$725.00
1	FRONT O/S FENDER GARNISH	TO REPAIR SEE LABOUR	\$280.60	\$0.00
1	FRONT O/S FENDER INNER SHIELD	NOT NECESSARY	\$235.80	\$0.00
1	FRONT O/S DOOR	DENTED	\$2,655.90	\$1,732.00
1	FRONT O/S DOOR CHROME MOULDING	TO REPAIR SEE LABOUR	\$245.00	\$0.00
1	REAR O/S DOOR	TO REPAIR SEE LABOUR	\$2,856.80	\$0.00
1	REAR O/S DOOR CHROME MOULDING	NOT NECESSARY	\$245.00	\$0.00
	LESS 25.00% DISCOUNT		(\$2,017.06)	(\$614.25)
			\$6,051.16	\$1,842.75

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT O/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$70.00	\$0.00
1	SUNDRY (SN)	NOT NECESSARY	\$50.00	\$0.00
			\$120.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WHEEL ALIGNMENT		\$80.00	\$0.00
	TO DISMANTLE AND REFIT THE INNER COMPARTMENT OF FRONT O/S DOOR TO NEW SHELL DOOR		\$150.00	\$50.00
	TO DISMANTLE AND REFIT THE INNER COMPARTMENT OF REAR O/S DOOR TO NEW SHELL DOOR		\$150.00	\$0.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST THE SAME ETC. INCLUSIVE OF THE REPAIR OF FRONT O/S FENDER GARNISH, FRONT O/S DOOR CHROME MOULDING AND REAR O/S DOOR		\$600.00	\$600.00
	TO PUTTY AND SPRAY PAINTING ON FRONT O/S FENDER, FRONT O/S DOOR, REAR O/S DOOR		\$1,050.00	\$800.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS		\$250.00	\$30.00
			\$2,280.00	\$1,480.00

GRAND TOTAL			\$8,451.16	\$3,322.75
--------------------	--	--	-------------------	-------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,650.00
Report Ref No: CS/INC24070343/Enh3e2			

TOTAL FOR SPARE PARTS: \$ 6,171.16 \$ 1,842.75
TOTAL FOR LABOUR : \$ 2,280.00 \$ 1,480.00
TOTAL REPAIR COST: \$ 8,451.16 \$ 3,322.75

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.