

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

QQ TECH AIRCON SERVICES
3 KAKI BUKIT INDUSTRIAL TERRACE
SINGAPORE 416091

Contact : 83434834

TP/NC
Veron

TAX INVOICE

Repair Code : CLM16367

Date in : 20/07/2024

Vehicle Num. : GBK900X

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011031411/1GD8473790

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT ADBLUE ECU At the end	1	3060.70	3,060.70
FRONT ADBLUE PIPE new	1	865.40	865.40
FRONT ADBLUE TANK to be changed	1	1066.60	1,066.60
X FRONT ADBLUE TANK UNDER COVER LH new	1	223.80	223.80
FRONT BONNET Repair	1	1082.50	1,082.50
FRONT BONNET 'LOGO' EMBLEM new	1	59.60	59.60
FRONT BONNET HINGES L/R new	2	62.30	124.60
FRONT BONNET INNER RUBBER STOPPER L/R new	2	18.40	36.80
FRONT BONNET MECHANISM LOCK new	1	99.80	99.80
FRONT BUMPER Distorted	1	573.60	573.60
FRONT BUMPER FOGLAMP GARNISH LH Missing	1	106.00	106.00
FRONT BUMPER INNER REINFORCEMENT VERTICAL BRACKET LH Best	1	157.00	157.00
FRONT BUMPER LOWER GRILLE Painted	1	188.70	188.70
FRONT BUMPER REINFORCEMENT new Distorted	1	379.40	379.40
FRONT BUMPER REINFORCEMENT BRACKET LH new	1	120.70	120.70
FRONT BUMPER SIDE RETAINER L/R 1st round	2	151.80	303.60
FRONT BUMPER TOW HOOK COVER L/R new HH 2nd	2	30.10	60.20
FRONT GRILLE BASE 1st	1	602.60	602.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

QQ TECH AIRCON SERVICES
3 KAKI BUKIT INDUSTRIAL TERRACE
SINGAPORE 416091

Contact : 83434834

TAX INVOICE

Repair Code : CLM16367

Date in : 20/07/2024

Vehicle Num. : GBK900X

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011031411/1GD8473790

FRONT GRILLE LOWER OUTER COVER	<i>Repair</i>	1	406.70	+	406.70
FRONT GRILLE TOP OUTER COVER	<i>new</i>	1	235.00	+	235.00
FRONT HEADLAMP LH	<i>ht</i>	1	791.40	✓	791.40
FRONT LH CORNER PANEL	<i>Dented</i>	1	284.60	-	284.60
FRONT LH CORNER PANEL BRACKET	<i>new</i>	1	60.10	+	60.10
FRONT LH DOOR	<i>Dented</i>	1	2245.20	<i>2089</i>	2,245.20
FRONT LH DOOR CHECKER	<i>new</i>	1	96.50	+	96.50
FRONT LH DOOR HINGE (LOWER)	<i>new But</i>	1	199.40	<i>95</i>	199.40
FRONT LH DOOR INNER ARCH SEAL	<i>new</i>	1	67.10	+	67.10
FRONT LH DOOR PILLAR (CENTER)	<i>Dented Repair</i>	1	573.70	+	573.70
FRONT LH DOOR PILLAR (OUTER)	<i>Dented Repair</i>	1	587.20	+	587.20
FRONT LH DOOR WIRE HARNESS	<i>new and d</i>	1	526.70	<i>2089</i>	526.70
FRONT LH DOOR WIRE HARNESS COVER	<i>new smashed</i>	1	256.00	✓	256.00
FRONT LH KNUCKLE ARM	<i>new</i>	1	948.10	<i>713</i>	948.10
FRONT LH KNUCKLE ARM BEARING	<i>new</i>	1	497.90	✓	497.90
FRONT LH LOWER ARM	<i>But</i>	1	945.90	<i>711</i>	945.90
FRONT LH SHOCK ABSORBER	<i>new</i>	1	172.50	+	172.50
FRONT LH STABILIZER LINK	<i>new</i>	1	294.90	+	294.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

QQ TECH AIRCON SERVICES
3 KAKI BUKIT INDUSTRIAL TERRACE
SINGAPORE 416091

Contact : 83434834

TAX INVOICE

Repair Code : CLM16367

Date in : 20/07/2024

Vehicle Num. : GBK900X

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011031411/1GD8473790

FRONT LH STEP GARNISH	lt	1	220.10	✓	220.10
FRONT LH TIE ROD END	new	1	229.00	+	229.00
FRONT LH UPPER ARM	new	1	1732.70	+	1,732.70
FRONT LH WHEEL CAP	Misc	1	288.20	✓	288.20
FRONT LH WHEEL RIM	new	1	598.50	+	598.50
FRONT WIRE HARNESS	build	1	2916.50	1688 ✓	2,916.50
LH CENTER DOOR PILLAR (OUTER)	Dented	1	707.40	✓	707.40
REAR BUMPER	lt	1	673.10	✓	673.10
REAR BUMPER SIDE RETAINER L/R	new	2	47.00	+	94.00
REAR LH FENDER	Dented	1	2315.40	✓	2,315.40
REAR LH TAILLAMP	new	1	458.10	+	458.10
REAR LH TAILLAMP LOWER GARNISH	Repair	1	127.70	+	127.70
REAR LH TAILLAMP LOWER GARNISH SIDE BRACKET	new	1	60.60	+	60.60
REAR LH WHEEL CAP	lt	1	288.20	✓	288.20
ROCKER PANEL LH	Repair	1	363.70	+	363.70
SLIDING DOOR LH	Dented	1	2860.40	✓	2,860.40

2055

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

QQ TECH AIRCON SERVICES
3 KAKI BUKIT INDUSTRIAL TERRACE
SINGAPORE 416091

Contact : 83434834

TAX INVOICE

Repair Code : CLM16367

Date in : 20/07/2024

Vehicle Num. : GBK900X

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011031411/1GD8473790

		Subtotal before discount	20696.10	32,234.10
Percentage discount 25%				8,058.53
		Sub-total 1	15522.07	24,175.58
FRONT BUMPER CLIPS - SET	NW	1	80.00	30 80.00
FRONT GRILLE CLIPS - SET	NW	1	40.00	20 40.00
FRONT LH DOOR CAMPANY STICKER	NW	1	25.00	✓ 25.00
FRONT LH STEP GARNISH CLIPS - SET	NW	1	30.00	✓ 30.00
FRONT LH TYRE	Cut	1	500.00	150 500.00
REAR BUMPER CLIPS - SET	NW	1	80.00	30 80.00
REAR LH FENDER WINDOW GLASS SEAL	NW	1	80.00	40 80.00
REAR LH FENDER WINDOW GLASS SEALANT	NW	1	80.00	30 80.00
REAR LH TAILLAMP LOWER GARNISH CLIPS - SET	NW	1	25.00	4 25.00
REAR LH TYRE	NW	1	500.00	4 500.00
SLIDING DOOR LH WINDOW GLASS SEAL	gme	1	80.00	40 80.00
SLIDING DOOR LH WINDOW GLASS SEALANT		1	80.00	30 80.00
		Subtotal before discount		1,600.00
Percentage discount 0%				0.00
		Sub-total 2		1,600.00
		Parts-total		25,775.58

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

QQ TECH AIRCON SERVICES
3 KAKI BUKIT INDUSTRIAL TERRACE
SINGAPORE 416091

Contact : 83434834

TAX INVOICE

Repair Code : CLM16367

Date in : 20/07/2024

Vehicle Num. : GBK900X

Model : TOYOTA HIACE DX 2.8 AUTO

Chassis/Eng# : GDH2011031411/1GD8473790

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change window glass.

To remove, reinstall fender glass

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To remove, reinstall petrol tank. (to FR)

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

30 80.00

X 500.00

✓ 80.00

40 150.00

40 150.00

200 380.00

80 100.00

X 80.00

50 180.00

60 160.00

1200 1,600.00

3360 1500 2,400.00

80 200.00

Labour Total

6,060.00

Parts & Labour Total

31,835.58

*** This is a computer-generated document which requires no signature. ***

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

page 5

Admin Lj
R/S 23/07/24

13 Days

total: 19307.67

L/S 15.4K

15.4K