

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunoss Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24060066/ENP3E2**Date:** 10/10/2024REFERENCE

Insured/Claimant:	TEO CHUN WEY	Policy No:	MP23A00353700	
Date of Loss:	08/06/2024	Nature of Claim:	OD	Claim No: DMPC2400719H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4362M		Engine No:	2NRX402869
Make & Model:	TOYOTA SIENTA, 1.5 (A)		Chassis No:	MHFZ28H3500060696
Reg. Date:	20/12/2018 (Man. Year: 2018)		Odometer:	114060 km
Colour:	Brown			
Engine Capacity:	1496 cc			
Market Value/New Car Price:	S\$77,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,219.21	11,457.74	5,761.47	33.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,984.00	5,597.20	2,386.80	29.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,203.21	17,054.94	8,148.27	32.33
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	25,203.21	16,554.94	8,648.27	34.31
+ GST 9.00/9.00% (S\$)	2,268.29	1,489.94	778.35	34.31
Nett Amount (S\$)	27,471.50	18,044.88	9,426.62	34.31

INSPECTION

Date of Assignment:	12/06/2024	Present Location:	Borneo Motors (S) Pte Ltd (Ubi)
Date Inspected:	13/06/2024	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4 Singapore 408611
Estimated Period of Repair:	8.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2024)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4362M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	S17700-0Y140	*CLEANER ASSY AIR W/	Not Necessary	1,494.00 FL	*- F
2	1	S16400-0Y130	*RADIATOR ASSY	Bent	3,040.80 FL	*2,128.56 F
3	1	S16711-0Y090	*SHROUD FAN	Not Necessary	411.10 FL	*- F
4	1	S88460-0D390	*CONDENSER ASSY	Bent	2,186.60 FL	*1,530.62 F
5	1	S88891-0D370	*COVER COOLER NO.1	Not Necessary	51.60 FL	*- F
6	1	S52119-0U928	*COVER FR BUMPER L/	Broken	515.20 FL	*360.64 F
7	1	S81482-0D290	*COVER FOG LAMP LH	Not Necessary	184.00 FL	*- F
8	1	S52144-0D120	*BRACKET FR BUMPER S	Broken	66.80 FL	*46.76 F
9	1	S52521-0D020	*RETAINER FR BUMPER	Broken	113.30 FL	*79.31 F
10	1	S53101-0D700	*GRILLE SUB-ASSY RAD	Broken	947.50 FL	*663.25 F
11	1	S52127-0D550	*COVER FR BUMPER HOL	Not Necessary	21.40 FL	*- F
12	4	S52161-0K040	*PIECE RR BUMPER	Necessary	23.20 FL	*16.24 F
13	1	S53301-0D260	*HOOD SUB-ASSY	Dented	913.20 FL	*639.24 F
14	1	S53812-0D220	*PANEL FR FENDER LH	Dented	883.80 FL	*618.66 F
15	1	S53828-0D170	*PROTECTOR FR FENDER	Not Necessary	65.70 FL	*- F
16	1	S53876-0D410	*LINER FR FENDER LH	Not Necessary	262.10 FL	*- F
17	1	S53510-0D640	*LOCK ASSY HOOD	Bent	188.00 FL	*131.60 F
18	1	S53420-0D642	*HINGE ASSY HOOD LH	Bent	92.50 FL	*64.75 F
19	1	S53410-0D642	*HINGE ASSY HOOD RH	Bent	92.50 FL	*64.75 F
20	1	S53201-0D200	*SUPPORT SUB-ASSY RA	Bent	1,605.00 FL	*1,123.50 F
21	1	S53208-0D140	*SUPPORT SUB-ASSY HO	Not Necessary	206.30 FL	*- F
22	1	S53203-0D090	*SUPPORT SUB-ASSY RA	Bent	109.40 FL	*76.58 F
23	1	S53202-0D080	*SUPPORT SUB-ASSY RA	Not Necessary	109.40 FL	*- F
24	1	S75301-0D160	*EMBLEM SUB-ASSY RAD	Necessary	93.30 FL	*65.31 F
25	1	T81130-52K31	*UNIT ASSY HEADLAMP	Not Necessary	5,286.10 FL	*- F
26	1	T81170-52K31	*UNIT ASSY HEADLAMP	Broken	4,952.00 FL	*3,466.40 F
27	1	S74404-0D240	*CLAMP SUB-ASSY BATT	Not Necessary	46.40 FL	*- F
Supplementary #1						
28	1	S53289-0D140	*COVER RADIATOR SUPP	Broken	201.00 FL	*140.70 F
29	1	S53286-0D310	*SEAL RADIATOR SIDE	Broken	67.30 FL	*47.11 F
30	1	S53288-0D210	*EXTENSION RADIATOR	Bent	60.80 FL	*42.56 F
31	2	S08889-80102	*COOLANT SLLC&&&	Necessary	216.00 FS	*151.20 F
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					24,506.30	11,457.74
- List Item Discount on L Items 30.00/0.00% (\$\$)					7,287.09	0.00
Total Parts (\$\$)					17,219.21	11,457.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SUNDRIES	New	100.00	50.00
2	CHECK WIRIN GAND REFOCUS HEADLAMP	New	158.40	158.40
3	SUPPLY REGN PLATE (PO#)	New	100.00	80.00
4	R/I AIRCOND PIPE VACCUM AND REGAS	New	316.80	316.80
5	TO RESET ECU AND REPROGRAMME	New	158.40	158.40
6	SUPPLY SEALANT (NETT)	New	200.00	200.00
7	REPL ACC AFF PARTS AND PANEL	New	3,801.60	2,534.40
8	RESRPAY ACC AFF AREA	New	3,148.80	2,099.20
Gross Labour Cost (S\$)			7,984.00	5,597.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >