

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070347/UUA3Q2**Date:** 11/10/2024**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04
Claimant Vehicle No : SLL1327X **Insured Vehicle No :** GBK3058H
Date of Loss: 19/07/2024 Nature of Claim: TP Claim No: MFL2024D0008532

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL1327X**
Make & Model: HONDA VEZEL, 1.5 1.5X CVT (A) Engine No: L15B4411584
Reg. Date: 15/02/2017 (Man. Year: 2016) Chassis No: RU11211584
Colour: Red Odometer: 123780 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,785.56	2,735.04	7,050.52	72.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,270.00	2,080.00	62.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,135.56	4,005.04	9,130.52	69.51
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	13,135.56	3,200.00	9,935.56	75.64
+ GST 9.00/9.00% (S\$)	1,182.20	288.00	894.20	75.64
Nett Amount (S\$)	14,317.76	3,488.00	10,829.76	75.64
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		3,815.25		

INSPECTION

Date of Assignment: 24/07/2024
Date Inspected: 24/07/2024 Inspected At: Carsmith Private Limited (HQ)
8 Kaki Bukit Ave 4, #04-35 Premier
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2024)
Parts:	M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL1327X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	1,654.00 FL	*566.10 FL
2	1		*REAR BUMPER RETAINER N/S	Not Necessary	98.00 FL	*- FL
3	1		*REAR BUMPER REFLECTOR N/S	Not Necessary	325.00 FL	*- FL
4	1		*REAR END PANEL	Repair	952.50 FL	*- FL
5	1		*REAR END PANEL STRIKER	Not Necessary	58.50 FL	*- FL
6	1		*REAR END PANEL LINING	Not Necessary	102.00 FL	*- FL
7	1		*TAILGATE	Dented / Bent	1,995.50 FL	*1,099.20 FL
8	1		*TAILLAMP N/S	Cracked	495.50 FL	*480.60 FL
9	1		*TAILGATELAMP N/S	Scratched	552.00 FL	*280.60 FL
10	1		*TAILGATE ABSORBER	Not Necessary	247.00 FL	*- FL
11	1		*TAILGATE LOGO	Serviceable	108.00 FL	*- FL
12	1		*TAILGATE WEATHERSTRIP	Not Necessary	295.00 FL	*- FL
13	1		*TAILGATE INNER BOARD	Deformed / Torn	855.00 FL	*281.30 FL
14	1		*TAILGATE INNER PULL POCKET	Not Necessary	108.60 FL	*- FL
15	1		*TAILGATE CENTRE CHROME	Not Necessary	225.00 FL	*- FL
16	1		*TAILGATE TRIMBOARD TOP	Not Necessary	158.70 FL	*- FL
17	2		*TAILGATE HINGE	Not Necessary	199.00 FL	*- FL
18	1		*REAR BUMPER SIDE LH	Deformed / Warped	280.40 FL	*280.40 FL
19	1		*TOOL SPONGE	Not Necessary	256.00 FL	*- FL
20	1		*REAR FENDER LH	Not Necessary	1,451.00 FL	*- FL
21	1		*REAR FENDER WHEEL ARCH LH	Torn	389.00 FL	*280.60 FL
22	1		*REAR FENDER INNER SHIELD LH	Not Necessary	325.00 FL	*- FL
23	1		*SET REAR WINDSCREEN SEALANT	Necessary	90.00 FS	*40.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
25	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET REVERSE SENSOR	Serviceable	480.00 FS	*- FS
27	1		*REAR BUMPER REFLECTOR RH	Not Necessary	151.00 FS	*- FS
28	1		*SET TAILGATE TRIMBOARD CLIPS	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,011.70	3,388.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,226.14	653.76
Total Parts (\$\$)	9,785.56	2,735.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	150.00	20.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	New	150.00	30.00
3	REMOVE & REFIT REAR WINDSCREEN	New	200.00	120.00
4	REMOVE AND REFIT REAR LINING ,TRIM AND GARNISH	New	150.00	0.00
5	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,300.00	550.00
6	SPRAY PAINTING ON AFFECTED AREAS	New	1,300.00	520.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	30.00
Gross Labour Cost (\$\$)			3,350.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >