8/1/24, 10:17 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI24070349/EVP3M4

Date: 01/08/2024

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MS001127 **Claimant Vehicle**

SHA3070C **Insured Vehicle No:** YM9649E No:

Date of Loss: 20/07/2024 Nature of Claim: ΤP Claim No: M2404071

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHA3070C Reg No:

HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Make & Model: Engine No: G4LEKU210456 14/05/2019 (Man. Year: 2019) KMHC851CVKU146088 Reg. Date: Chassis No:

Colour: Blue Odometer: 846948 km

Engine Capacity: 1580 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes **Engine Modification:** Pre-accident Condition: Handbrake (Serviceable): Yes Nο Average

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,824.56	1,422.08	402.48	22.06
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	700.00	660.00	40.00	5.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,536.56	2,094.08	442.48	17.44
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	2,536.56	1,650.00	886.56	34.95
+ GST 9.00/9.00% (S\$)	228.29	148.50	79.79	34.95
Nett Amount (S\$)	2,764.85	1,798.50	966.35	34.95

INSPECTION

Date of Assignment: 22/07/2024 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 23/07/2024 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: **VERON CHEN** Manager: CHEN TSUE YEE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Aug 2024)

Parts: 143 HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHA3070C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER ASSY	Repair	481.10 FL	*- FL
2	10		*FRT BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*FRT RADIATOR GRILLE	Broken	1,409.10 FL	*1,409.10 FL
4	1		*FRT BUMPER CENTRE MOULDING	Cut	368.50 FL	*368.50 FL
F=Fra	anchise	part. L=ListIte	mDisc.	_		
				Sub Total (S\$)	2,280.70	1,777.60
			- List Item Discount o	n L Items 20.00/20.00% (S\$)	456.14	355.52
				Total Parts (S\$)	1,824.56	1,422.08
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 OD/TP Case (Insurer)		12.00	12.00
	Sub Total (S\$)	12.00	12.00
Pacammandad Labour			

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	400.00	380.00
2	SPRAYPAINT	New	300.00	280.00
		Gross Labour Cost (S\$)	700.00	660.00
Report was unsubmitted during this print-out				

< END OF ESTIMATES >