

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/ICS24070350/UQH3E2**Date:** 13/08/2024REFERENCE

Handling Insurer: ECICS Limited Policy No:

**Claimant Vehicle No :** SME5335X **Insured Vehicle No :** YQ6362E

Date of Loss: 20/07/2024 Nature of Claim: TP Claim No: DMCF2400033H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME5335X**

Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGJU239517

Reg. Date: 03/10/2018 (Man. Year: 2018) Chassis No: KMHD841CMJU730649

Colour: Red Odometer: 109774 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,976.94	3,490.08	6,486.86	65.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,510.00	2,230.00	59.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>13,716.94</b>	<b>5,000.08</b>	<b>8,716.86</b>	<b>63.55</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>Nett Amount (\$\$)</b>	<b>13,716.94</b>	<b>4,000.00</b>	<b>9,716.94</b>	<b>70.84</b>

INSPECTION

Date of Assignment: 23/07/2024

Date Inspected: 23/07/2024 Inspected At: Blk 15 Kaki Bukit Road 4, Bartley Biz Centre #01-53  
Singapore 417808  
Repairer: Zoom Autowerks Pte Ltd

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2024)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME5335X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented / Bent	2,049.80 FL	*2,032.00 FL
2	2		*REAR BOOT HINGES	Not Necessary	275.60 FL	*- FL
3	1		*REAR BOOT LAMPS	N/S Not Necessary/ O/S Cracked	725.00 FL	*295.10 FL
4	1		*REAR BOOT LOCK	Serviceable	250.80 FL	*- FL
5	1		*REAR BOOT LOGO	Necessary	97.80 FL	*48.00 FL
6	1		*REAR BOOT ELANTRA EMBLEM	Necessary	90.90 FL	*48.80 FL
7	2		*REAR TAILLAMPS	Not Necessary	801.00 FL	*- FL
8	1		*REAR END PANEL	Repair	557.50 FL	*- FL
9	1		*REAR END PANEL INNER GARNISH	Not Necessary	299.30 FL	*- FL
10	1		*REAR SMART KEYLESS SENSOR	Not Necessary	217.80 FL	*- FL
11	1		*REAR BUMPER	Cracked	688.74 FL	*481.40 FL
12	2		*REAR BUMPER TOP BRACKETS	Not Necessary	131.60 FL	*- FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	199.60 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	455.80 FL	*294.80 FL
15	2		*REAR BUMPER REINFORCEMENT STAY	Not Necessary	401.60 FL	*- FL
16	3		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	434.70 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	181.94 FL	*- FL
18	1		*REAR BUMPER UNDERCOVER	Not Necessary	155.80 FL	*- FL
19	1		*REAR FLOOR BOARD	Not Necessary	259.10 FL	*- FL
20	1		*REAR BOOT SPOILER	Cracked	850.00 FS	*500.00 FS
21	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*REAR BUMPER LOWER SPOILER	Cracked	750.00 FS	*400.00 FS
23	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
24	1		*SET REAR REVERSE SENSOR	Serviceable	350.00 FS	*- FS
25	1		*REAR REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,804.38	4,130.10
- List Item Discount on L Items 10.00/20.00% (\$\$)	827.44	640.02
Total Parts (\$\$)	9,976.94	3,490.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	30.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	50.00
5	TO APPLY UNDERCOATING	New	150.00	30.00
6	PANEL BEATING	New	1,600.00	500.00
7	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	880.00
<b>Gross Labour Cost (\$)</b>			<b>3,740.00</b>	<b>1,510.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >