

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24070351/AVP3M4**Date:** 09/01/2025**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001456961		
Claimant Vehicle No :	SMJ9019G	Insured Vehicle No :	SFZ9813D		
Date of Loss:	22/07/2024	Nature of Claim:	TP	Claim No:	367755

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ9019G	Engine No:	4J11AC8662
Make & Model:	MITSUBISHI OUTLANDER, 2.0 CVT (A)	Chassis No:	GF7W0600740
Reg. Date:	25/03/2019 (Man. Year: 2018)	Odometer:	152824 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,895.70	5,584.00	5,311.70	48.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,980.00	1,920.00	2,060.00	51.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,875.70	7,504.00	7,371.70	49.56
Approved Total (Overridden) (S\$)		5,720.00		
Nett Amount (S\$)	14,875.70	5,720.00	9,155.70	61.55

INSPECTION

Date of Assignment:	24/07/2024	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER SINGAPORE 415933
Date Inspected:	23/07/2024 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2025)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ9019G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP	Not Necessary	116.00 FL	*- FL
2	1		*REAR BUMPER	Deformed	816.00 FL	*816.00 FL
3	1		*REAR BUMPER SIDE HOLDER	N/S Cracked	64.00 FL	*32.00 FL
4	1		*REAR BUMPER IMPACT BRACKET	N/S Dented	210.00 FL	*105.00 FL
5	1		*REAR BUMPER LOWER GARNISH	Deformed	289.00 FL	*289.00 FL
6	1		*REAR BUMPER REFLECTOR	N/S Cracked	196.00 FL	*98.00 FL
7	1		*REAR END PANEL	Dented	526.00 FL	*526.00 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	146.00 FL	*146.00 FL
9	1		*REAR END PANEL BUZZER	Not Necessary	182.00 FL	*- FL
10	1		*REAR END PANEL ANTENNA SENSOR	Cracked	196.00 FL	*196.00 FL
11	1		*TAILLAMP	N/S Cracked	1,012.00 FL	*506.00 FL
12	1		*TAILGATE	Distorted	884.00 FL	*884.00 FL
13	1		*TAILGATE LOCK	Damaged	385.00 FL	*385.00 FL
14	1		*TAILGATE WEATHERSTRIPE	Torn	192.00 FL	*192.00 FL
15	1		*TAILGATE REFLECTOR	N/S Cracked	794.00 FL	*397.00 FL
16	1		*TAILGATE INNER TRIM BOARD	Cracked	352.00 FL	*352.00 FL
17	1		*TAILGATE OUTER GARNISH	Cracked	446.00 FL	*446.00 FL
18	1		*TAILGATE GLASS MOULDING	Necessary	161.00 FL	*161.00 FL
19	1		*MITSUBISHI LOGO	Necessary	41.00 FL	*41.00 FL
20	1		*OUTLANDER EMBLEM	Necessary	86.00 FL	*86.00 FL
21	1		*MIVEC EMBLEM	Necessary	52.00 FL	*52.00 FL
22	2		*FLOOR PANEL	Not Necessary	895.00 FL	*- FL
23	1		*FLOOR PANEL TOP BOARD	Not Necessary	455.00 FL	*- FL
24	1		*TOOLS TRAY	Not Necessary	289.00 FL	*- FL
25	1		*SPARE TYRE CARRIAGE	Not Necessary	386.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM	Not Necessary	1,352.00 FL	*- FL
27	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*- FS
28	1		*REAR NUMBER PLATE HOLDER	Not Necessary	30.00 FS	*- FS
29	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
30	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
31	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
33	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	30.00 FS	*30.00 FS
34	1		*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
35	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
36	1		*CYCLE & CARRIAGE LOGO	Necessary	45.00 FS	*45.00 FS
37	1		*FLOOR PANEL INSULATION PAD	Not Necessary	280.00 FS	*- FS
38	2		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	60.00 FS	*- FS
39	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	11,948.00	6,155.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,052.30	571.00
Total Parts (\$)	10,895.70	5,584.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	1,600.00	700.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,400.00	700.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
5	TO REMOVE REVERSE SENSOR	New	100.00	50.00
6	TO REMOVE UPHOLSTERY	New	150.00	80.00
7	TO REMOVE REAR CAMERA	New	100.00	50.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
9	TO REMOVE TAILGATE GLASS	New	180.00	120.00
10	TO REMOVE REAR VIDEO RECORDER	New	100.00	50.00
Gross Labour Cost (\$\$)			3,980.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >