



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070353/Anh3e2
16 RAFFLES QUAY	Date:	22/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 2913S	Veh. Inspected	SNJ 6443Y
Policy No.	D24102455MFVT	Coverage	0
Claim No.	D24006316MFVT	Excess	\$0.00
Assign From	HARMINDER KAUR	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	PEUGEOT 5008	C.C	1199
Engine No.	10XTA40888306	Year of Reg.	29/03/2018
Chassis No.	VF3MRHNYWHL077063	Colour	GREY
Odometer	128559 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/60 R17	BRIDGESTONE	6
L/H Front Tyre	225/60 R17	BRIDGESTONE	6
R/H Rear Tyre	225/60 R17	BRIDGESTONE	6
L/H Rear Tyre	225/60 R17	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/07/2024	Inspection Date	23/07/2024
Survey held at	SM AUTOMOTIVE - BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days