

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNC 3230B

	REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	HEADLAMP RH	NOT NECESSARY	\$1,200.00	\$0.00			
1	FRONT BUMPER	NOT NECESSARY	\$685.00	\$0.00			
2	FRONT BUMPER SIDE RETAINER LH & RH	NOT NECESSARY	\$120.00	\$0.00			
1	FRONT BUMPER CLIPS	NOT NECESSARY	\$50.00	\$0.00			
1	FRONT FENDER RH	DENTED	\$660.00	\$660.00			
1	FRONT FENDER COWLING RH	NOT NECESSARY	\$140.00	\$0.00			
1	FRONT FENDER COWLING CLIPS	NOT NECESSARY	\$50.00	\$0.00			
1	FRONT FENDER BKT FRT RH	NOT NECESSARY	\$60.00	\$0.00			
1	WASHER TANK	NOT NECESSARY	\$190.00	\$0.00			
1	FRONT DOOR RH	DENTED	\$920.00	\$920.00			
2	FRONT DOOR HINGE UPPER & LOWER	NOT NECESSARY	\$240.00	\$0.00			
1	FRONT DOOR CHECKER	NOT NECESSARY	\$155.00	\$0.00			
1	FRONT DOOR POWER WINDOW MOTOR	NOT NECESSARY	\$360.00	\$0.00			
1	FRONT DOOR POWER WINDOW REGULATOR	NOT NECESSARY	\$390.00	\$0.00			
1	FRONT DOOR INNER TRIMBOARD	NOT NECESSARY	\$455.00	\$0.00			
1	FRONT DOOR INNER LOCK	NOT NECESSARY	\$680.00	\$0.00			
1	FRONT DOOR WEATHERSTRIP (AT DOOR)	NOT NECESSARY	\$80.00	\$0.00			
1	FRONT DOOR WEATHERSTRIP (AT BODY)	NOT NECESSARY	\$215.00	\$0.00			
2	FRONT DOOR TAPE FRT & RR	NECESSARY	\$80.00	\$80.00			
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	\$195.00	\$0.00			
1	FRONT DOOR OUTER HANDLE COVER	NOT NECESSARY	\$160.00	\$0.00			
1	SIDE MIRROR RH	NOT NECESSARY	\$630.00	\$0.00			
1	SIDE MIRROR COVER RH	NOT NECESSARY	\$190.00	\$0.00			
1	SIDE MIRROR LOWER COVER RH	NOT NECESSARY	\$150.00	\$0.00			
1	FRONT DOOR PILLAR RH	NOT NECESSARY	\$980.00	\$0.00			
1	FRONT DOOR QTR GLASS MLDG RH	NOT NECESSARY	\$285.00	\$0.00			
1	FRONT WHEEL BEARING RH	DAMAGED	\$270.00	\$270.00			
1	FRONT WHEEL HUB RH	NOT NECESSARY	\$480.00	\$0.00			
1	FRONT KNUCKLE ARM RH	NOT NECESSARY	\$820.00	\$0.00			
1	FRONT LOWER ARM RH	NOT NECESSARY	\$530.00	\$0.00			



# **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	REPLACEMEN	T OF PARTS		
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	\$430.00	\$0.00
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	NOT NECESSARY	\$120.00	\$0.00
1	FRONT SHOCK ABSORBER TOP MOUNTING BEARING RH	NOT NECESSARY	\$60.00	\$0.00
1	FRONT STABILIZER BAR	NOT NECESSARY	\$550.00	\$0.00
1	FRONT DRIVE SHAFT RH	NOT NECESSARY	\$830.00	\$0.00
1	FRONT STEERING RACK	NOT NECESSARY	\$2,450.00	\$0.00
1	FRONT CROSSMEMBER	NOT NECESSARY	\$800.00	\$0.00
1	FRONT RH RIM	NOT NECESSARY	\$1,320.00	\$0.00
	LESS 10.00% DISCOUNT		(\$1,798.00)	(\$193.00)
			\$16,182.00	\$1,737.00
	Special	Nett		
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH TYRE (SN)	NOT NECESSARY	\$550.00	\$0.00
			\$550.00	\$0.00
	Labo	our		
	Description of Parts	Condition		
		Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING	Continuon	Workshop Estimate (\$) \$40.00	Sur Adjusted (\$)
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER	Continuon		, , , ,
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING	Containon	\$40.00	\$30.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW	Contained	\$40.00 \$150.00	\$30.00 \$80.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	NOT NECESSARY	\$40.00 \$150.00 \$180.00	\$30.00 \$80.00 \$60.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR  TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH		\$40.00 \$150.00 \$180.00 \$400.00	\$30.00 \$80.00 \$60.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR  TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT		\$40.00 \$150.00 \$180.00 \$400.00 \$250.00	\$30.00 \$80.00 \$60.00 \$0.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR  TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT  TO DISMANTLE ALL DAMAGED PARTS		\$40.00 \$150.00 \$180.00 \$400.00 \$250.00 \$1,500.00	\$30.00 \$80.00 \$60.00 \$0.00 \$400.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR  TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT  TO DISMANTLE ALL DAMAGED PARTS		\$40.00 \$150.00 \$180.00 \$400.00 \$250.00 \$1,500.00 \$1,500.00	\$80.00 \$60.00 \$60.00 \$400.00 \$600.00
	SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING  TO CHECK AND RE-ADJUST WHEEL ALIGNMENT  TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR  TO DISMANTLE; REPLACE AND REINSTALL UNDERCARRIAGE. FRT LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT  TO DISMANTLE ALL DAMAGED PARTS  TO SPRAY PAINT DAMAGED PORTION		\$40.00 \$150.00 \$180.00 \$400.00 \$250.00 \$1,500.00 \$1,500.00 \$4,020.00	\$30.00 \$80.00 \$60.00 \$0.00 \$400.00 \$600.00 \$1,230.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

### **LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.