



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKW 7216Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DISTORTED / TORN	\$995.00	\$995.00
1	FRONT BUMPER BEAM	NOT NECESSARY	\$517.20	\$0.00
1	FRONT BUMPER LAMP N/S	CRACKED	\$266.50	\$266.50
1	FRONT BUMPER FOG LAMP N/S	CRACKED	\$378.00	\$378.00
1	FRONT BUMPER FOG LAMP GARNISH N/S	TORN	\$142.60	\$142.60
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	\$56.20	\$56.20
1	SET FRONT BUMPER CLIPS	NECESSARY	\$50.00	\$50.00
1	FRONT BUMPER LOWER LIP (CUT)	NOT CONSISTENT WITH THE IMPACT	\$650.00	\$0.00
1	FRONT FENDER N/S	DENTED / BENT	\$334.00	\$334.00
1	FRONT FENDER INNER SHIELD N/S	TWISTED	\$112.30	\$112.30
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	\$30.00	\$30.00
1	FRONT GRILLE ASSY	NOT NECESSARY	\$527.50	\$0.00
1	HEADLAMP N/S	CRACKED	\$2,976.00	\$2,976.00
1	HEADLAMP PANEL N/S	TO REPAIR SEE LABOUR	\$250.50	\$0.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	\$588.30	\$0.00
1	FRONT SPORT RIM N/S	TO REPAIR SEE LABOUR	\$1,100.00	\$0.00
1	FRONT LOWER ARM N/S	NOT NECESSARY	\$366.20	\$0.00
1	FRONT KNUCKLE ARM N/S	NOT NECESSARY	\$381.50	\$0.00
1	FRONT KNUCKLE ARM BEARING N/S	NOT NECESSARY	\$188.50	\$0.00
	LESS 20.00% DISCOUNT		(\$1,982.06)	(\$1,068.12)
			\$7,928.24	\$4,272.48

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK WIRING		\$50.00	\$20.00
	TO RESET & DIAGNOSTIC SYSTEM	NOT NECESSARY	\$180.00	\$0.00
	TO SPRAY RUST PROOFING		\$50.00	\$30.00
	TO CONDUCT WHEEL ALIGNMENT		\$100.00	\$60.00
	TO DISMANTLE FRONT UNDER CARRIAGE	NOT NECESSARY	\$180.00	\$0.00
	TO REFILL AIR CON GAS	NOT NECESSARY	\$120.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL N/S AND FRONT SPORT RIM N/S.		\$680.00	\$400.00
	TO PUTTY & SPRAY PAINTING		\$880.00	\$600.00
			\$2,240.00	\$1,110.00
GRAND TOTAL			\$10,168.24	\$5,382.48
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$4,300.00
Report Ref No: CS/INC24060067/Uqh3				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser