

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24060067/Uqh3e2	
	75 BRAS BASAH R		Date:	12/06/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.					
	Insured Veh.	SMZ 2083G	Veh. Inspected	SKW 7216Y	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1281169-002	Excess	\$0.00	
	Assign From	SITI RAUDHAH	Assign Date	12/06/2024	
2.	2. Vehicle Details				
	Make & Model	MAZDA 3 SP (A)	C.C	1496	
	Engine No.	P520327670	Year of Reg.	12/11/2015	
	Chassis No.	JM6BM42A8G0322940	Colour	GREEN	
	Odometer	146132 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: S/RIM	-		
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/45R17	GOODYEAR	6	
	L/H Front Tyre	225/45R17	GOODYEAR	6	
	R/H Rear Tyre	225/45R17	GOODYEAR	6	
	L/H Rear Tyre	225/45R17	GOODYEAR	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	08/06/2024	Inspection Date	13/06/2024 (10:22 AM)	
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883			
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
ECTIMATED MODIMAL DEDICE FOR DEDAID. A Working David					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days