

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	CE LTD		Ref:	CS/INC24070365/Avh3e2(N)	
	75 BRAS BASAH R INCOME CENTRES	OAD BINGAPORE 189557		Date:	22/01/2025	
	ATTN: NATALIE LE	E		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMA 6252R	Veh. Inspected	t	SMT 7259R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1287220-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		23/07/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SHUTTLE HYBRID	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	GP72000331	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/55 R15	YOKOHAMA		6 mm	
	L/H Front Tyre	195/55 R15	YOKOHAMA		6 mm	
	R/H Rear Tyre	195/55 R15	YOKOHAMA		6 mm	
	L/H Rear Tyre	195/55 R15	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	21/07/2024	Inspect Date /	Time	24/07/2024 (11:39 AM)	
	Survey held at					
		8 KAKI BUKIT AVENUE 4 #03-33 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 24 Working Days				