

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24060068/EQP3E2**Date:** 11/07/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH000482
Claimant Vehicle No :	SHC8246U	Insured Vehicle No :	GBD8205D
Date of Loss:	10/06/2024	Nature of Claim:	TP
		Claim No:	M2403265

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8246U		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU415636
Reg. Date:	08/01/2021 (Man. Year: 2019)	Chassis No:	KMHC851CVLU191821
Colour:	Blue	Odometer:	186402 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,262.08	492.32	2,769.76	84.91
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,410.00	870.00	540.00	38.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,684.08	1,374.32	3,309.76	70.66
Approved Total (Overridden) (\$\$)		1,100.00		
(\$\$)	4,684.08	1,100.00	3,584.08	76.52
+ GST 9.00/9.00% (\$\$)	421.57	99.00	322.57	76.52
Nett Amount (\$\$)	5,105.65	1,199.00	3,906.65	76.52

INSPECTION

Date of Assignment:	11/06/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	12/06/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2024)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC8246U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	481.10 FL	*- FL
2	1		*FRONT BUMPER GRILLE LH	Not Necessary	186.90 FL	*- FL
3	1		*FRONT DAY RUNNING LIGHT LH	Not Necessary	642.50 FL	*- FL
4	1		*FRONT BUMPER BRACKET LH	Not Necessary	41.40 FL	*- FL
5	1		*FRONT FENDER LH	Dented	588.80 FL	*588.80 FL
6	1		*HEADLAMP LH	Not Necessary	2,110.30 FL	*- FL
7	1		*FRONT FENDER EMBLEM	Necessary	26.60 FL	*26.60 FL
					Sub Total (S\$)	4,077.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	815.52
					Total Parts (S\$)	3,262.08

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK LIGHTING	New	60.00	20.00
Gross Labour Cost (\$)			1,410.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >