

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LIBERTY INSURANCE PTE LTD			Ref:	CS/LIP24070366/Dvh3
	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	19/08/2024
SINGAPORE 048583		33	Code:	LIP
1.	Policy Particulars :- THIRD PARTY CLAIM			
1.	Insured Veh.	GBK 4853Y	Veh. Inspected	SLB 5539C
	Policy No.	-	Coverage	0
	Claim No.	AVS24/2284	Excess	\$0.00
	Assign From	ANDY SEAH	Assign Date	24/07/2024
2.	Vehicle Details			
	Make & Model	TOYOTA HARRIER	c.c	1986
	Engine No.	3ZRB683919	Year of Reg.	13/04/2016
	Chassis No.	ZSU600065396	Colour	WHITE
	Odometer	121727 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	235/50R19	PIRELLI	6
	L/H Front Tyre	235/50R19	PIRELLI	6
	R/H Rear Tyre	235/50R19	PIRELLI	6
	L/H Rear Tyre	235/50R19	PIRELLI	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	21/07/2024	Inspection Date	24/07/2024
	Survey held at	DETAIL LAB BLK 8 KAKI BUKIT AVE 4 #02-03/04 PREMIER @ KB SINGAPORE 415875		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days