



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070371/Anp3e2
16 RAFFLES QUAY	Date:	10/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1214H	Veh. Inspected	GBG 8234D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006002MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	23/07/2024

2. Vehicle Details

Make & Model	NISSAN CABSTAR	C.C	2953
Engine No.	ZD30026639N	Year of Reg.	06/11/2017
Chassis No.	JN1SC2F24Z0860378	Colour	BLUE
Odometer	247577 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15C	BRIDGESTONE	6
L/H Front Tyre	195 R15C	BRIDGESTONE	6
R/H Rear Tyre	155 R13C	ARIVO	6
L/H Rear Tyre	155 R13C	ARIVO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2024	Inspection Date	23/07/2024
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days