

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070374/KMA3Q2**Date:** 17/10/2024**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056556-06
Claimant Vehicle No : SNR49A **Insured Vehicle No :** SJJ121M
Date of Loss: 22/07/2024 Nature of Claim: TP Claim No: 1664264025SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNR49A**
Make & Model: TESLA MODEL 3 PERFORMANCE, (A) Engine No: HIDDEN
Reg. Date: 03/09/2021 (Man. Year: 2021) Chassis No: LRW3F7ELXMC283029
Colour: Metallic Pearl White Odometer: 56270 km
Engine Capacity: 0 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35Z R20 Rear Tyre Size: 285/30Z R20
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,808.38	1,463.99	344.39	19.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	980.00	470.00	510.00	52.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,788.38	1,933.99	854.39	30.64
+ GST 9.00/9.00% (S\$)	250.95	174.06	76.89	30.64
Nett Amount (S\$)	3,039.33	2,108.05	931.28	30.64
+ Loss of Use (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		33.18		
Nett Liability (S\$)		2,341.23		
Global Sum Settlement (S\$)		2,340.00		

INSPECTION

Date of Assignment: 24/07/2024
Date Inspected: 24/07/2024 Inspected At: Optima Werkz Pte Ltd (HQ)
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Autopoint
Singapore 568047
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	766.00 FL	*766.00 FL
2	1		*REAR BUMPER LOWER	Mtg Cracked	140.18 FL	*140.18 FL
3	1		*REAR BUMPER CENTER BRACKET	Cracked	52.33 FL	*52.33 FL
4	1		*REAR BUMPER REINFORCEMENT	Buckled	271.02 FL	*271.02 FL
5	1		*REAR REVERSE SENSOR	Dented / Shorted (1 PCS ONLY)	490.65 FL	*163.55 FL
			(3 PCS)			
6	6		*REAR REVERSE SENSOR MOUNTING BRACKET	Necessary	28.02 FL	*28.02 FL
7	1		*REAR BUMPER CLIPS	Necessary	55.00 FS	*55.00 FS
8	1		*REAR BUMPER LOWER CLIPS	Not Necessary	50.00 FS	*- FS
9	1		*TO RE-COAT OF REAR BUMPER	Necessary	130.00 FS	*130.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	1,983.20	1,606.10
- List Item Discount on L Items 10.00/10.00% (\$)	174.82	142.11
Total Parts (\$)	1,808.38	1,463.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	450.00	180.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ETC	New	350.00	220.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	60.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	10.00
Gross Labour Cost (\$\$)			980.00	470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >