

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No.

19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS/FCI24070376/Kvp3e2
	16 RAFFLES QUAY #42-01 HONG LEONG BUILDING		Date:	10/09/2024
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2
1.	. Policy Particulars :- OWN DAMAGE CLAIM			
	Insured Veh.	-	Veh. Inspected	QY 120D
	Policy No.	D-24102282MFQC/2	Coverage	0
	Claim No.	D24006340MFQC	Excess	\$0.00
	Assign From	CAROLINE	Assign Date	24/07/2024
2. Vehicle Details				
	Make & Model	TOYOTA CAMRY (A)	c.c	2494
	Engine No.	2ARU335565	Year of Reg.	11/07/2016
	Chassis No.	MR053CK5004020285	Colour	METALLIC SILVER
	Odometer	63691 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/55ZR17	DAVANTI	8
	L/H Front Tyre	215/55ZR17	DAVANTI	8
	R/H Rear Tyre	215/55ZR17	DAVANTI	8
	L/H Rear Tyre	215/55ZR17	DAVANTI	8
4.				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	19/07/2024	Inspection Date	24/07/2024
	Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.		
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$45,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL DEDIOD FOR DEDAID: 2 Working Davis				

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days