

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : OD

Vehicle No. : QY120D

Make & Model : Toyota Camry

Year of Manufacture : 2016

Chassis No. : MR053CK5004020285

Engine No. : 2ARU335565

Policy No. : D-24102282MFQC/2

Time of Accident : 1030

Ins Company : MS First Capital

Excess :

Date of Accident : 19.07.24

Suggested Days of Repair : 5

In-house Vehicle Assessor

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,427.00

Plus/Less 20% \$ 685.40

Total of Cost / List \$ 2,741.60

(b) Nett Price Items \$ -

Less

Total of Nett Item

(c) Special Nett Items \$ 50.00

Total Parts Cost (Appendix A) \$ 2,791.60

Labour (Appendix B) \$ 1,100.00

Total Repair Cost \$ 3,891.60

Case Owner :

Signature :

Contact No

Operation

KELVIN SU

TEL: 9786 4236

E: kelvinsukwen@cdqe.com.sg

JOHARI

TEL: 972103705

E: joharibh@sparkcarcare.com

SUN PIN

TEL: 9728 8916

E: oisunpin@cdqe.com.sg

*Not Authorized
Primary Repair*

The above total will be subjected to 8% G.S.T.

Name of Surveyor : Kennerh

Company : CDQE

Survey conducted on : 24/7/24 at

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : ☒ Required / Not Required

(d) Excess : \$ TBA

(e) Signature of surveyor : Le Date: 24/7/24

Spare Parts

Vehicle No : QY120D Case Owner : 0
Make & Model : Toyota Camry Year Manufactur : 2016
Chassis No : MR053CK5004020285 Engine No : 2ARU335565
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : OD

| No | Part Description | QTY | Cost Price | List Price | Nett Price | S/N | Disposition By Surveyor |
|----|-----------------------------|-----|------------|-------------|-------------|-----|-------------------------|
| 1 | Front Bumper | | CMA | \$ 960.00 | | | ✓ |
| 2 | Front Bumper Lower Grille | | CM | \$ 1,032.00 | | | ✓ |
| 3 | Lower Grille Chrome Garnish | | RM | \$ 280.00 | | | ✓ |
| 4 | Front Bumper Lower Garnish | | RM | \$ 260.00 | | | ✓ |
| 5 | Front Bumper Tow Cover | | SN | \$ 70.00 | | | X |
| 6 | Front Bmper No Plate Base | | CM | \$ 250.00 | | | ✓ |
| 7 | RHF Fog Lamp Cover | | RM | \$ 215.00 | | | ✓ |
| 8 | Front Parking Sensor | | | \$ 360.00 | | | 7 |
| 9 | Number plate + casing set | | | | RM \$ 50.00 | | 45 SN |
| 10 | | | | | | | |
| 11 | | | | | | | |
| 12 | | | | | | | |
| 13 | | | | | | | |
| 14 | | | | | | | |
| 15 | | | | | | | |
| 16 | | | | | | | |
| 17 | | | | | | | |
| 18 | | | | | | | |
| 19 | | | | | | | |
| 20 | | | | | | | |
| 21 | | | | | | | |
| 22 | | | | | | | |
| 23 | | | | | | | |
| 24 | | | | | | | |
| 25 | | | | | | | |
| 26 | | | | | | | |
| 27 | | | | | | | |
| 28 | | | | | | | |
| 29 | | | | | | | |
| 30 | | | | | | | |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Parts \$ 3197
S/N \$ 45

LABOR \$ 495