

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CTI24070378/TQP3E2**Date:** 10/10/2024REFERENCEInsured/Claimant: JIANG KEVIN TRANSPORTATION
SERVICES

Policy No: DMB1SNW00016612305

Date of Loss: 17/07/2024

Nature of
Claim: ODClaim
No: SNM24D204152/C01/TAYHPDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PC5067U**

Make & Model: ISUZU LT434P 7.8 SMT, 7.8 D (M)

Engine No: 6HK1663725

Reg. Date: 25/06/2015 (Man. Year: 2014)

Chassis No: JALLT434PE7000095

Colour: White

Odometer: 0 km

Engine Capacity: 7790 cc

Market Value/New Car Price: S\$36,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5

Rear Tyre Size: 295/80 R22.5 (D)

Front Left Side: Firemax 8 mm

Rear Left Side: Firemax 8/8 mm

Front Right Side: Firemax 8 mm

Rear Right Side: Firemax 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	58,385.00	50,247.00	8,138.00	13.94
Miscellaneous Items	666.00	506.00	160.00	24.02
Labour	6,350.00	5,500.00	850.00	13.39
Paintwork Labour	1,000.00	1,000.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	66,401.00	57,253.00	9,148.00	13.78
Approved Total (Overridden) (S\$)		30,000.00		
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	66,401.00	28,000.00	38,401.00	57.83
+ GST 9.00/9.00% (S\$)	5,976.09	2,520.00	3,456.09	57.83
Nett Amount (S\$)	72,377.09	30,520.00	41,857.09	57.83

INSPECTION

Date of Assignment: 26/07/2024

Date Inspected: 24/07/2024 Inspected At:

17 Kranji Link

Repairer: Century Motors (Singapore) Pte Ltd (HQ)

Estimated Period of Repair: 30.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Oct 2024)	
Parts:	N/A	ISUZU LT434P 7.8 SMT 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC5067U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT WINDSCREEN LOWER	Cracked	6,200.00 F	*6,200.00 FL
2	1		*FRT WINDSCREEN RUBBER MOULDING	Necessary	850.00 F	*850.00 FL
3	1		*FRT UPPER WINDSCREEN	Cracked	3,600.00 F	*3,600.00 FL
4	1		*FRT UPPER WINDSCREEN INNER SEAL	Necessary	450.00 F	*450.00 FL
5	1		*FRT UPPER FRAME STRUCTURE	Bent	2,900.00 F	*2,900.00 FL
6	1		*ROOF OUTER PANEL (FRT HALF PORTION)	Cracked	9,000.00 F	*9,000.00 FL
7	1		*FRT PANEL	Cracked	4,200.00 F	*4,200.00 FL
8	1		*FRT PANEL INNER STRUCTURE	Bent	1,550.00 F	*1,550.00 FL
9	1		*FRT FACE STRUCTURE	Bent	3,700.00 F	*3,700.00 FL
10	1		*FRT LH TOP LAMP	Cracked	250.00 F	*250.00 FL
11	1		*WIPER LINKAGE	Bent	850.00 F	*850.00 FL
12	1		*FRT LH REAR VIEW MIRROR ASSY	Broken	1,450.00 F	*1,450.00 FL
13	1		*FRT LH PILLAR BEAM INNER	Bent	1,050.00 F	*1,050.00 FL
14	1		*FRT LH PILLAR OUTER	Bent	1,200.00 F	*1,200.00 FL
15	1		*FRT DASHBOARD	Distorted	3,800.00 F	*3,800.00 FL
16	1		*FRT LH ENTRANCE DOOR	Bent	2,250.00 F	*2,250.00 FL
17	1		*FRT LH STEP PANEL STRUCTURE	Not Necessary	1,400.00 F	*- FL
18	1		*FRT LH ENTRANCE DOOR STEEL MOULDING	Deformed	980.00 F	*980.00 FL
19	1		*FRT CENTER WINDSCREEN CASING GUARD	Cracked	1,300.00 F	*1,300.00 FL
20	1		*FRT LH LINKAGE	Bent	1,300.00 F	*1,300.00 FL
21	1		*FRT VENTER INTERIOR PARTITION	Distorted	2,200.00 F	*2,200.00 FL
22	1		*FRT BUMPER	Cracked	2,250.00 F	*2,250.00 FL
23	1		*FRT BUMPER INNER STRUCTURE	Bent	950.00 F	*950.00 FL
24	1		*FRT BUMPER LH BRACKET	Bent	380.00 F	*380.00 FL
25	1		*FRT BUMPER FOG LAMP LH	Not Necessary	285.00 F	*- FL
26	1		*FRT LH WIPER BLADE	Cut	85.00 F	*85.00 FL
27	1		*FRT RH WIPER BLADE	Cut	85.00 F	*85.00 FL
28	1		*FRT LH WIPER ARM HUB COVER	Distorted	115.00 F	*115.00 FL
29	1		*FRT RH WIPER ARM HUB COVER	Not Necessary	115.00 F	*- FL
30	1		*FRT RH WIPER ARM	Not Necessary	155.00 F	*- FL
31	1		*FRT LH WIPER ARM	Bent	155.00 F	*155.00 FL
32	1		*FRT LH HEAD LAMP	Cracked	1,750.00 F	*1,750.00 FL
33	1		*FRT GRILLE	Cracked	980.00 F	*980.00 FL
34	1		*FRT GRILLE CHROME GARNISH	Not Necessary	370.00 F	*- FL
35	1		*FRT GRILLE INNER STRUCTURE	Not Necessary	230.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	58,385.00	55,830.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	5,583.00
Total Parts (S\$)	58,385.00	50,247.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	ERP BRACKET (NECESSARY)	26.00	26.00
2	1	FRT NUMBER PLATE (CRACKED)	40.00	30.00
3	1	SEALANT (NECESSARY)	600.00	450.00
Sub Total (S\$)			666.00	506.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAY PAINTING MULTI COLOR & DESIGN	New	1,000.00	1,000.00
Labour Items				
2	CHECK WIRING	New	100.00	50.00
3	LABOUR CHARGES TO REMOVE & REFIT FRT LOWER WINDSCREEN	New	1,000.00	800.00
4	LABOUR CHARGES TO REMOVE & REFIT FRT UPPER WINDSCREEN	New	1,000.00	800.00
5	LABOUR CHARGES TO REMOVE & REFIT DASHBAORD TO ASSIST REPAIR	New	350.00	350.00
6	LABOUR CHARGES TO REMOVE & REFIT INTERIOR LH TRIMS,CENTER PARTITION,UPHOLSTERY ETC TO ASSIST REPAIR	New	600.00	500.00
7	LABOUR CHARGES TO TRANSFER ENTRANCE DOOR FITTINGS TO ASSIST REPAIR	New	300.00	300.00
8	LABOUR CHARGES	New	3,000.00	2,700.00
Gross Labour Cost (S\$)			7,350.00	6,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >