

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 31 Jul 2024

**Preliminary Advice**

Vehicle No	: PC5067U	Accident Date	: 17/07/2024
Make	: ISUZU LT434P 7.8 SMT	Policy No.	: DMB1SNW00016612305
Assignment Date	: 26/07/2024	Excess	: S\$2,000.00
Date of Inspection	: 25/07/2024	Est. Duration of Repair	: 30
Inspection At	: CENTURY MOTORS (SINGAPORE) PTE LTD (HQ) 6 MARSILING LANE, SINGAPORE 739145		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	66,401.00
Revised Amount	:S\$	62,836.00
Check Items (Estimated)	:S\$	2,000.00
Total	:S\$	64,836.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	36,000.00
COE / PARF Rebate	:S\$	4,663.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,000.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer able to undertake the repair cost at \$30,000.00 on Lump Sum basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.