Accident Repair Estimate

ACCIDENT DATE:

17-Jul-24

BUS NUMBER:

SBS8659Z

ACCIDENT TIME:

0536Hrs

BUS MODEL:

WSD

ACCIDENT REPORT NUMBER:

AR-2024-3861

DATE OF SURVEY:

25-Jul-24

3RD PARTY CLAIM AGAINST:

PC5067U

SECTION A: PARTS & MATERIAL COST			
Post on Mary Description	O	Total Cost	
Part or Item Description	Quantity	Total cost	
REAR WINDSCREENSN C&D 500 STREET CONTROL OF SERIES CONTROL OF SE			
BUMPER.REAR.F/G.C&D SERIES (A)			
RR LAMP PANEL;O/S			
LED TAIL/STOP LAMP			
LED INDICATOR LAMP			
LED REVERSE LAMP			
REFLEX REFLECTOR MAS			
STKR SBS TRANSIT RR SD/DD SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY			
REAR FRAME PILLAR; RR FRAME			
ATTACHMENT BRACKET BOTTOM;RR FRAME 51/			
SKID SHOE @ K;RR FRAME CAL			
VERTICAL PILLAR @ KL+KR;SIDE FRAME ?			
GAS JACK 0400N; RR ENG DOOR 6+ CILCT RH			
LIMIT SWITCH;ADJUSTABLE @ RR ENG DR 54/			
FLUID RESERVOIR;HYD.PMP			
COMPARTMENT HINGE LHS 1@ HL			
COMPARTMENT HINGE RHS 1@ JL			
11.677			
3/4			
	TOTAL PARTS & MATERIAL COST	\$0.00	
SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOU	JR COST)	
Assessment of Bus (With Damaged)		\$188.00	
To Remove / Replace / Repair Damaged Parts by Contractor		\$3,800.00	
To Remove/ Replace/ Repair Damaged Advertisement Panel		\$0.00	
	TOTAL LABOUR COST	\$3,988.00	
SECTION C:	SUMMARY		
SECTION C:	JOIVINALL		
Total Repair Costs		\$3,988.00	
Total Downtime (Days)	5	\$2,040.50	
Towing Cost		\$0.00	
Total Overheads Costs		\$1,196.40	
*Please kindly note that the downtime (days) is just an estimate	TOTAL COST	\$7,224.90	
*Please undersign to acknowledge this repair estimate.	-	у — <u>— — — — — — — — — — — — — — — — — —</u>	
		Passer - Ho 900 cools	
Prepared by:	Surveyor Name & Contact:	place - # \$ 100,000.0	
Trepared by.	Buiveyor Hame & Conde		
		W Can	
Signature:	Signature:	3000/	
-			
		125/07/24	
Date:	Date:	0) 0 (0	

enail: rasul@lkkauto.com

Accident Repair Estimate

ACCIDENT DATE:

17-Jul-24

BUS NUMBER:

SBS8659Z

ACCIDENT TIME:

0536Hrs

BUS MODEL:

WSD

ACCIDENT REPORT NUMBER:

AR-2024-3861

DATE OF SURVEY:

25-Jul-24

\$3,333.76

3RD PARTY CLAIM AGAINST:

PC5067U

SECTION A:	PARTS & MATERIAL COST	PARTS & MATERIAL COST		
Part or Item Description	Quantity	Total Cost		
REAR WINDSCREENSN C&D	1	\$170.00		
REAR DOOR;F/GLASS;C & C+ SERIES	1	\$523.00		
BUMPER.REAR.F/G.C&D SERIES	1	\$305.00		
RR LAMP PANEL;O/S	1	\$162.00		
LED TAIL/STOP LAMP	2	\$194.40		
LED INDICATOR LAMP	1	\$102.20		
LED REVERSE LAMP	1	\$105.60		
REFLEX REFLECTOR	1	\$1.35		
STKR SBS TRANSIT RR SD/DD	1	\$6.00		
SIDE PANEL JR~KR.O/S.SIDE PANEL ASSY	1	\$250.00		
REAR FRAME PILLAR;RR FRAME	1	\$153.00		
ATTACHMENT BRACKET BOTTOM;RR FRAME	1	\$57.14		
SKID SHOE @ K;RR FRAME	11	\$56.70		
VERTICAL PILLAR @ KL+KR;SIDE FRAME	1	\$228.60		
GAS JACK 0400N;RR ENG DOOR	2	\$52.00		
LIMIT SWITCH;ADJUSTABLE @ RR ENG DR	1	\$23.13		
FLUID RESERVOIR;HYD.PMP	1	\$180.49		
COMPARTMENT HINGE LHS 1@ HL	1	\$122.10		
COMPARTMENT HINGE RHS 1@ JL	1	\$122.10		
DOOR FRAME JR~KR;O/S;ALUM;A/B/C SERIES	1	\$163.80		
NSULATION 01;CPSS25;25MMX1MX2M;WIRING	1	\$149.13		
NSULATION HOLDER 01;1.0MM ALUM SHEET N	1	\$33.42		
ALUM WIRE MESH;ENG DR;1PC=1.8M N	1	\$172.60		

SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)		
Assessment of Bus (With Damaged)		\$188.00	
To Remove / Replace / Repair Damaged Parts by Contractor To Remove/Replace/Repair Damaged Advertisement Panel		\$3,800.00 \$0.00	

TOTAL PARTS & MATERIAL COST

SECTION C:	SUMMARY	
Total Repair Costs		\$7,321.76
Total Downtime (Days)	5	\$2,040.50
Towing Cost		\$0.00
Total Overheads Costs		\$2,196.53
*Please kindly note that the downtime (days) is just an estimate.	TOTAL COST	\$11,558.79
*Please undersign to acknowledge this repair estimate.		

Prepared by:	ERIC NG Snr Technical Officer Ulu Pandan Workshop	Surveyor Name & Contact:	
Signature:	Bus Engineering	Signature:	-
Date:	22/2/24	Date:	