

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070385/APA3Q2**Date:** 24/12/2025REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230024498
Claimant Vehicle No : FZ616R **Insured Vehicle No :** GBJ1559Y
 Date of Loss: 16/07/2024 Nature of Claim: TP Claim No: 2788799142SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FZ616R**
 Make & Model: HONDA ADV750, 745cc ABS AUTO Engine No: RH10E5008136
 Reg. Date: 26/07/2021 (Man. Year: 2021) Chassis No: JH2RH10A9MK007982
 Colour: Red Odometer: 18934 km
 Engine Capacity: 745 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,880.00	1,526.00	1,354.00	47.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	430.00	570.00	57.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,880.00	1,956.00	1,924.00	49.59
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	3,880.00	1,500.00	2,380.00	61.34
+ Loss of Use (3.0 x S\$25.00/day) (S\$)		75.00		
Nett Liability (S\$)		1,575.00		

INSPECTION

Date of Assignment: 23/07/2024
 Date Inspected: 23/07/2024 Inspected At: Ms Car Auto Pte Ltd (HQ)
 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT
 Singapore 415875
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR MUDFLAP	Cut	135.00 FL	*135.00 FL
2	2		*REAR SIGNAL LAMP	Not Necessary	90.00 FL	*- FL
3	1		*REAR EXHAUST PIPE	Repair	780.00 FL	*- FL
4	1		*REAR EXHAUST PIPE HEAT SHIELD	Cut	185.00 FL	*185.00 FL
5	1		*REAR SLIDER	Cut	145.00 FL	*145.00 FL
6	1		*REAR FOOTREST	Cut	110.00 FL	*110.00 FL
7	1		*BALANCER	Cut	85.00 FL	*85.00 FL
8	1		*HAND LEVER PROTECTOR	Cracked	285.00 FL	*285.00 FL
9	1		*SIDE FAIRING (RED)	Repair	390.00 FL	*- FL
10	1		*FRONT SIGNAL LAMP	Cracked	105.00 FL	*105.00 FL
11	1		*FRONT WING MIRROR	Cut	90.00 FL	*90.00 FL
12	1		*REAR NUMBER PLATE	Not Necessary	20.00 FS	*- FS
13	1		*GRASH BAR (GIVI)	Cut	700.00 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,120.00	1,640.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	240.00	114.00
Total Parts (\$\$)	2,880.00	1,526.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	400.00	200.00
2	SPRAY PAINTING	New	400.00	150.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REAR EXHAUST PIPE	New	150.00	50.00
Gross Labour Cost (\$\$)			1,000.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >