



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNC 2354J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DISTORTED	\$980.00	\$872.00
1	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	\$62.40	\$0.00
1	FRONT BUMPER LOWER SPOILER	CUT	\$520.00	\$520.00
1	FRONT BUMPER LOWER SPOILER GUARD	CUT	\$150.00	\$150.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	\$80.00	\$0.00
1	FRONT BUMPER LOWER GRILLE	CRACKED	\$190.00	\$190.00
1	FRONT BUMPER REINFORCEMENT	DENTED	\$420.00	\$387.00
1	FRONT BUMPER DAYLIGHT	CRACKED	\$580.00	\$395.00
1	FRONT BUMPER DAYLIGHT HOUSING	CRACKED	\$90.00	\$90.00
2	FRONT BUMPER SENSOR @\$320.00	NOT NECESSARY	\$640.00	\$0.00
2	FRONT BUMPER SENSOR O RING @\$20.00	NOT NECESSARY	\$40.00	\$0.00
1	FRONT GRILLE ASSY	CRACKED	\$1,055.30	\$942.00
1	HEADLAMP	CRACKED	\$2,855.30	\$2,180.00
1	HEADLAMP LOWER BRACKET	CRACKED	\$80.00	\$80.00
1	FRONT FENDER	DENTED	\$520.00	\$520.00
1	FRONT FENDER INNER COWLING	DEFORMED	\$190.00	\$190.00
1	FRONT FENDER WHEEL ARCH	DEFORMED	\$220.00	\$220.00
1	SUPPORT PANEL	NOT NECESSARY	\$820.00	\$0.00
1	WASHER TANK	DEFORMED	\$250.00	\$110.00
	<b>LESS 20.00% DISCOUNT</b>		(\$1,948.60)	(\$1,369.20)
			<b>\$7,794.40</b>	<b>\$5,476.80</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER PLATE (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	\$20.00	\$20.00
1	SET FRONT BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	\$20.00	\$20.00
1	SET FRONT FENDER INNER COWLING CLIPS (SN)	NECESSARY	\$22.00	\$22.00
1	SET FRONT FENDER WHEEL ARCH CLIPS (SN)	NECESSARY	\$20.00	\$20.00
1	WHEEL RIM (SN)	CUT	\$1,000.00	\$400.00
			<b>\$1,132.00</b>	<b>\$482.00</b>



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS	NOT NECESSARY	\$1,200.00	\$400.00
	TO SPRAY PAINT AFFECTED AREA		\$1,000.00	\$400.00
	TUFF COAT		\$250.00	\$40.00
	WIRING CHECK		\$100.00	\$30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$250.00	\$0.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$100.00	\$50.00
	WHEEL ALIGNMENT		\$100.00	\$80.00
			\$3,000.00	\$1,000.00
GRAND TOTAL			\$11,926.40	\$6,958.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$5,500.00
Report Ref No: CS/INC24060007/Aqp3				

TOTAL FOR SPARE PARTS: \$ 8,926.40 \$ 5,958.80  
TOTAL FOR LABOUR : \$ 3,000.00 \$ 1,000.00  
TOTAL REPAIR COST: \$11,926.40 \$ 6,958.80

**LWP**

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.