

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070386/AMA3Q2**Date:** 17/01/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800103126
Claimant Vehicle No : SME4861A **Insured Vehicle No :** SMD6386Y
Date of Loss: 20/07/2024 Nature of Claim: TP Claim No: 7071120074SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME4861A**
Make & Model: VOLKSWAGEN TOURAN, 1.4 1.4 TSI CL 5T13NZ HLG (A) Engine No: CZD168619
Reg. Date: 30/09/2018 (Man. Year: 2018) Chassis No: WVGZZZ1TZKW001389
Colour: Blue Odometer: 66387 km
Engine Capacity: 1395 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,120.57	7,216.34	13,904.23	65.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,010.00	930.00	4,080.00	81.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,130.57	8,146.34	17,984.23	68.82
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	26,130.57	6,500.00	19,630.57	75.12
+ GST 9.00/9.00% (S\$)	2,351.75	585.00	1,766.75	75.12
Nett Amount (S\$)	28,482.32	7,085.00	21,397.32	75.12
+ Car Rental (3.0 x S\$100.00/day + 9.00% GST) (S\$)		327.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		7,439.25		
Global Sum Settlement (S\$)		7,400.00		

INSPECTION

Date of Assignment: 23/07/2024
Date Inspected: 23/07/2024 Inspected At: HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875
Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,635.00 FL	*1,509.00 FL
2	1		*FRONT BUMPER FOGLAMP RH	Not Necessary	541.80 FL	*- FL
3	1		*FRONT BUMPER FOGLAMP COVER RH	Not Necessary	342.60 FL	*- FL
4	1		*FRONT BUMPER FOGLAMP LOWER GARNISH RH	Not Necessary	186.40 FL	*- FL
5	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	328.60 FL	*- FL
6	1		*FRONT BUMPER SIDE LOWER GARNISH RH	Not Necessary	189.40 FL	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	O/S Cracked	310.60 FL	*155.30 FL
8	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	874.80 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Not Necessary	190.60 FL	*- FL
10	1		*FRONT GRILLE WITH LOGO (UPPER)	Not Necessary	842.73 FL	*- FL
11	1		*FRONT CENTER GRILLE	Not Necessary	534.90 FL	*- FL
12	1		*HEADLAMP RH	Cracked	4,195.00 FL	*3,455.00 FL
13	1		*FRONT FENDER RH	Dented	1,567.90 FL	*990.00 FL
14	1		*FRONT FENDER INNER COWLING (UPPER) RH	Not Necessary	285.10 FL	*- FL
15	1		*FRONT FENDER INNER COWLING (LOWER) RH	Not Necessary	197.30 FL	*- FL
16	1		*FRONT FENDER SUPPORT BRACKET RH	Not Necessary	120.99 FL	*- FL
17	1		*FRONT WHEEL RIM RH	Cut	1,346.96 FS	*800.00 FS
18	1		*FRNT ABS SENSOR RH	Not Necessary	446.63 FL	*- FL
19	1		*FRONT KNUCKLE ARM RH	Not Necessary	689.77 FL	*- FL
20	1		*FRONT LOWER ARM RH	Bent	489.33 FL	*489.33 FL
21	1		*FRONT KNUCKLE ARM BEARING RH	Damaged	497.30 FL	*497.30 FL
22	1		*FRONT STABILIZER BAR LINKAGE RH	Not Necessary	139.77 FL	*- FL
23	1		*FRONT DRIVESHAFT RH	Not Necessary	2,009.73 FL	*- FL
24	1		*FRONT SHOCK ABSORBER RH	Not Necessary	499.77 FL	*- FL
25	1		*FRONT STEERING RACK AND PINION	Not Necessary	3,887.99 FL	*- FL
26	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
27	1		*SET FRONT BUMPER SIDE GARNISH CLIP RH	Not Necessary	60.00 FS	*- FS
28	1		*SET FRONT BUMPER UNDER COVER CLIP	Not Necessary	80.00 FS	*- FS
29	1		*SET FRONT GRILLE (LOWER) CLIP	Not Necessary	60.00 FS	*- FS
30	1		*SET FRONT FENDER INNER COWLING (UPPER) CLIP	Not Necessary	50.00 FS	*- FS
31	1		*SET FRONT FENDER INNER COWLING (LOWER) CLIP	Not Necessary	50.00 FS	*- FS
32	1		*FRONT WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
33	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,220.97	7,925.93
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,100.40	709.59
Total Parts (\$\$)	21,120.57	7,216.34

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,200.00	500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	250.00	0.00
4	WIRING CHECK	New	180.00	30.00
5	REFOCUS HEADLAMP BEAM	New	80.00	0.00
6	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
7	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	0.00
9	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	450.00	0.00
10	RESET ABS LIGHT	New	350.00	0.00
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	650.00	0.00
Gross Labour Cost (\$\$)			5,010.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >