

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24070387/APA3Q2**Date:** 05/05/2025**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100349878
Claimant Vehicle No :	GBL9622J	Insured Vehicle No :	GBC8861P
Date of Loss:	10/05/2024	Nature of Claim:	TP
		Claim No:	1742716694SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBL9622J	Engine No:	HIDDEN
Make & Model:	BYD ET3, (A)	Chassis No:	LC0CE4DB6N0065661
Reg. Date:	12/08/2022 (Man. Year: 2022)	Odometer:	0 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16C	Rear Tyre Size:	195/60 R16C
Front Left Side:	Linglong 6 mm	Rear Left Side:	Linglong 6 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Linglong 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	39,996.30	16,106.49	23,889.81	59.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,400.00	2,320.00	3,080.00	57.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,396.30	18,426.49	26,969.81	59.41
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	45,396.30	14,000.00	31,396.30	69.16
+ GST 9.00/9.00% (S\$)	4,085.67	1,260.00	2,825.67	69.16
Nett Amount (S\$)	49,481.97	15,260.00	34,221.97	69.16
+ Loss of Use (12.0 x S\$80.00/day) (S\$)		960.00		
+ Doc/Search Fee (S\$)		31.00		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		16,351.00		

INSPECTION

Date of Assignment:	23/07/2024		
Date Inspected:	23/07/2024	Inspected At:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	12.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Not Necessary	1,560.80 F	*- FL
2	1		*FRONT FENDER SIGNAL LAMP RH	Not Necessary	70.50 F	*- FL
3	1		*FRONT FENDER INNER COWLING RH	Not Necessary	245.00 F	*- FL
4	1		*FRONT FENDER QUARTER GLASS RH	Not Necessary	285.90 F	*- FL
5	1		*SIDE MIRROR RH	Smashed	987.50 F	*987.50 FL
6	1		*FRONT DOOR RH	Distorted	6,578.20 F	*3,600.00 FL
7	1		*FRONT DOOR OUTER HANDLE RH	Damaged	385.90 F	*385.90 FL
8	1		*FRONT DOOR OUTER HANDLE COVER RH	Damaged	68.90 F	*68.90 FL
9	1		*FRONT DOOR INNER TRIM RH	Cracked	965.30 F	*740.00 FL
10	1		*FRONT DOOR INNER LOCK RH	Jammed	785.60 F	*785.60 FL
11	1		*FRONT DOOR WEATHERSTRIP RH (DOOR)	Cut	398.50 F	*398.50 FL
12	1		*FRONT DOOR WEATHERSTRIP RH (FRAME)	Not Necessary	387.20 F	*- FL
13	1		*FRONT DOOR INNER STEP GARNISH RH	Not Necessary	245.60 F	*- FL
14	1		*FRONT DOOR STOPPER	Not Necessary	38.50 F	*- FL
15	1		*FRONT DOOR GLASS REGULATOR RH	Damaged	987.50 F	*450.00 FL
16	1		*FRONT DOOR GLASS REGULATOR MOTOR RH	Not Necessary	925.30 F	*- FL
17	1		*FRONT DOOR OUTER MOULDING RH	Deformed	398.50 F	*240.00 FL
18	1		*SIDE PILLAR ENTIRE FRAME RH	Dented	12,458.90 F	*3,210.00 FL
19	1		*SIDE DOOR RH	Distorted	7,256.30 F	*3,750.00 FL
20	1		*SIDE DOOR INNER LOCK RH	Damaged	987.60 F	*510.00 FL
21	1		*SIDE DOOR LATCH RH	Not Necessary	48.90 F	*- FL
22	1		*SIDE DOOR LOWER ROLLER	Jammed	398.50 F	*398.50 FL
23	1		*SIDE DOOR UPPER ROLLER	Damaged	325.70 F	*325.70 FL
24	1		*SIDE DOOR HANDLE RH	Damaged	298.50 F	*298.50 FL
25	2		*SIDE DOOR STOPPER RH	Not Necessary	90.00 F	*- FL
26	1		*SIDE DOOR HANDLE COVER RH	Damaged	65.30 F	*65.30 FL
27	1		*SIDE DOOR PANEL GARNISH	Not Necessary	385.20 F	*- FL
28	1		*SIDE DOOR WEATHERSTRIP (FRAME)	Torn	405.90 F	*405.90 FL
29	1		*SIDE DOOR INNER TRIM RH	Cracked	625.80 F	*625.80 FL
30	1		*SET FRONT DOOR INNERTRIM CLIPS	Necessary	40.00 FS	*30.00 FS
31	1		*SET SIDE DOOR INNERTRIM CLIP	Necessary	40.00 FS	*30.00 FS
32	1		*SET SIDE PILLAR SEALANT	Necessary	300.00 FS	*100.00 FS
33	1		*REAR FENDER COVER BOARD RH	Cracked	480.00 FS	*200.00 FS
34	1		*SIDE DOOR COVER BOARD RH	Cut	450.00 FS	*200.00 FS
35	1		*FRONT DOOR COMPANY MARKER	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	39,996.30	17,831.10
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,724.61
Total Parts (\$\$)	39,996.30	16,106.49

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,WELD ,CUT ADJUST KNOCK	New	2,600.00	1,200.00
2	TO SPRAY PAINT TO AFFECTED AREA	New	2,200.00	1,000.00
3	TO TRANSFER SIDE DOOR MECHANISM	New	200.00	60.00
4	TO TRANSFER FRONT DOOR MECHANISM	New	200.00	60.00
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,CHECK WIRING	New	200.00	0.00
Gross Labour Cost (\$\$)			5,400.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >